



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM
Ready for Pickup: Thu Apr 9, 2026 | 8:47 AM
Promise Time: Sun Apr 12, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER 16BHX-452
5ZT2AVEC7TG815781
1 Mi In
Stock #: FR26-25

Service Advisor
KEVIN GOODIEL
goodielk

A.	MISCELLANEOUS	DEALER STATES THE TOP HINGE ON CABINET DOOR UNDER KITCHEN SINK IS BROKEN	Internal Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. Cabinet door may have opened during transport and swung open past the designed amount

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.25	0	0	\$0.00	\$0.00

1. Needs new hinge. Requested .3 hours

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES THE PLUMBING VENT CAP SCREW AND RIGHT REAR CORNER EXTRUSION REQUIRE RESEAL	Internal Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. Small holes in self leveling sealant.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM
Ready for Pickup: Thu Apr 9, 2026 | 8:47 AM
Promise Time: Sun Apr 12, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER 16BHX-452
5ZT2AVEC7TG815781

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.08	0	0	\$0.00	\$0.00

1. Re-sealed plumbing vent and right corner rear extrusion.

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C.	MISCELLANEOUS	DEALER STATES UNIT DIDNT COME WITH A SEPTIC CAP FOR THE WAIST TANKS	Internal Pay	\$0.00
----	---------------	---	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. missing

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00

1. Unit missing septic cap. Requested .1 hours

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

D.	MISCELLANEOUS	DEALER STATES THE CABINET DOOR BYE KITCHEN SINK HAS A BIG SCUFF IN IT	Internal Pay	\$0.00
----	---------------	---	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM
Ready for Pickup: Thu Apr 9, 2026 | 8:47 AM
Promise Time: Sun Apr 12, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER 16BHX-452
5ZT2AVEC7TG815781

Service Advisor
KEVIN GOODIEL
goodielk

1. Cabinet door may have swung open past designed amount during transport. Cabinet broke top hinge and made 2 large gouges on outside of cabinet door at bottom hinge.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00

1. Needs new door. Requested .3 hours

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

Category	Sale	Cost
Labor	\$0.00	\$0.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM
Ready for Pickup: Thu Apr 9, 2026 | 8:47 AM
Promise Time: Sun Apr 12, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 FOREST RIVER
AVENGER 16BHX-452
5ZT2AVEC7TG815781

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Apr 7, 2026	3:07 PM	3:22 PM	0.25 hrs	I	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Apr 7, 2026	4:07 PM	4:12 PM	0.08 hrs	I	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	-	-	-	0 hrs	I	shurterc	0 hrs
D	MISC	-	-	-	0 hrs	I	shurterc	0 hrs

