



Claim CLAIM92600 (C3935886)

Last Modified By

										Changed		
Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	warranty rate	Type	Date of Purchase	
CLAIM92600 (C3935886)	40189	4/1/2026	4/1/2026	4YDFALP24TE780170	PA03983837	16105	Link Ford & RV Minong LLC 1025 Hokah St Minong, WI 54859	165.00	0.00	WARR	1/1/1970	

Deny code	Item number	Name	Quantity	Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	211112	Warranty Shop Supply - Fasteners - Screws - Staples - Bolts and Etc.	1	0	2.00	30.00	2.60	0.00	0.00	0.00	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3100102A	Base Cabinets - Repair	1.3	1.3	214.5	0	1	0.2	Approved
Complaint Dealer states that the cabinet next to the refrigerator is stuck closed. Cause Cabinet is stuck shut due to the shelves falling off pins and getting pinched inside the cabinet. Correction Had to use a pry-bar to remove the cabinet face, revealing that the shelves had fallen off their pins and pinched the cabinet slider shut. With a pry-bar, I adjusted the cabinets to be able to fully open. To prevent the issue from recurring, I sued a pocket hole jog to add a screw to each shelf. I then reinstalled the cabinet face and tested the cabinet. *This is not a flat rate job due to the extensive work that needed to be done just to get the door to open and adjusted the shelving.*									

Submitted parts & subLet	2.60	Approved parts & subLet	2.60
Submitted labor & subLet	214.50	Approved labor & subLet	214.50
Submitted freight	0.00	Approved freight	0.00
Total Submitted	217.10	Total approved	217.10