

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Authorized
 CLAIM 2655467
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TSAR2XTJ048759
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 003 / 003A
 ITEM # SAT389HBFL
 DEALER RO # 26243
 CLAIM START DATE 04/27/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$175.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-100-24-00-004416 Hidden Pantry Face/Door - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2026-04-27 11:16:32 :: Complaint: Small holes across the hidden
 pantry Cause: Noted on DAF, holes not filled at install Correction: Fill, color, and blend
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$35.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$35.00
Notes
 Auth per expired claim 2475029.

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-24-00-001050 Cabinet Stiles - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2026-04-27 11:19:26 :: Complaint: Stile next to microwave is
 chipped in 3 places Cause: Noted on DAF Correction: Fill chipped areas in and color blend
Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$52.50
Serial# **Appr Hrs** 0.30 **Appr Labor Amt** \$52.50
Notes
 auth per expired claim 2475029.

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-24-00-001050 Cabinet Stiles - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2026-04-27 11:22:38 :: Complaint: Stile above panel at entry of unit
 has the color faded off Cause: Noted on DAF Correction: Fill and blend color in this area
Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$52.50
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$35.00
Notes
 Auth per expired claim 2475029.

Labor

Line# 4 **Operation Code** **Operational Description**
 30-101-24-00-001074 Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No
 Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2026-04-27 11:25:30 :: Complaint: Where the door trim was
 installed left rough holes and makes trim look damaged Cause: Noted on DAF Correction: Smooth holes, fill, and
 color blend
Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$52.50

