



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26845



WO #: 26845

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11281
 Stock Desc: 2026 TT KEYSTONE
 BULLETCROSSFIRE 2530RD
 Model: 2530RD
 Serial #: 4YDTBLM26TD431652
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 17 MAR 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 30 APR 26
 Warr. Date:

Job #1 - Warranty

COMPLAINT: CABINETS OVER BED HAVE 2 SPOTS WHERE PAINT IS SCRATCHED/CHIPPED

CAUSE: DAMAGED AT FACTORY
 NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS
 LABOR .30

Labor

Job #	Description	Hours	Total
1	FILL AND COLOR	0.20	35.00
Subtotal for Job #1:			35.00

Job #2 - Warranty

COMPLAINT: REAR LIGHT STRIPS ON THE LEFT AND RIGHT SIDE OF UNIT WILL NOT WORK

CAUSE: FAULTY LIGHT STRIPS ON REAR OF UNIT
 LIGHTS WILL NOT COME ON

CORRECTION: REMOVE AND REPLACE BOTH LIGHT STRIP
 LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED	0.60	105.00

Parts

Part #	Description	Qty	Price	Total
739905	LIGHT STRIP	2.00	44.19	88.38

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	16.04	16.04

Subtotal for Job #2: 209.42

Job #3 - Warranty

COMPLAINT: BLACK TRIM HAS PAINT ON IT ABOVE THE EXIT DOOR

CAUSE: NOTED ON DAF

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



CORRECTION: COLOR AND BLEND AREA
LABOR .30

Labor

Job #	Description	Hours	Total
3	COLOR AND BLEND	0.20	35.00

Subtotal for Job #3: 35.00

Job #4 - Warranty

COMPLAINT: BEDROOM HAS 2 SCRATCHES ON IT

CAUSE: NOTED ON DAF
SCRATCHED AT BUILD

CORRECTION: COLOR AND BLEND AREA
LABOR .30

Labor

Job #	Description	Hours	Total
4	COLOR AND BLEND	0.20	35.00

Subtotal for Job #4: 35.00

Job #5 - Warranty

COMPLAINT: KITCHEN CABINETS OVER THE SINK ARE TOUCHING AND NOT CLOSING
CORRECTLY

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGE SO DOOR CLOSSES CORRECTLY
LABOR .40

Labor

Job #	Description	Hours	Total
5	ADJUST HINGE	0.20	35.00

Subtotal for Job #5: 35.00

Parts Total: 88.38
Labour Total: 245.00
Sublet Total: 0.00
Extras Total: 16.04
WORK ORDER TOTAL: 349.42

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Apr 2026

W/O: 26845



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

