

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79038
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 50528 - AMY J. STOTLAR
Address: 2425 GLENVIEW DR EVANSVILLE, IN

47720

Phone: 812-306-7135

Stock Number: 11573 - 2025 CATALINA 243RBSLE 5ZT2CANB6SN301263

VIN: 5ZT2CANB6SN301263 HIN: SER#: 5ZT2CANB6SN301263

Mileage: 0 Work Order Comp: 23 MAR 26

Auth. No: Dealer #:

Warr. Date: 21 FEB 26 Work Order Date: 16 FEB 26 Inv #: 427748

WO #	Job #	Description	JOB INFORMATION
79038	3	NOT GETTING RECEPTION FROM TV ANTENNA Tv no antenna reception Took power booster out and antenna off and put my tester on the cable coming from antenna to booster and factory had the wrong cable in the wrong place on the booster. They had white cable and the purple cable flipped. So after i flipped them the Antenna works properly now. Put antenna back on and booster back in the wall. All good now	
79038	4	BOTH FRONT LED LIGHTS HAVE AREAS THAT ARE NOT WORKING AND NEEDS REPLACED Both led cap lights had lights not working Took off old non working lights and replaced them with new ones. And then i wired them up and sealed the top. Lights work properly now.	

Part No	Job#	Description	PARTS	Qty	Price	Total
F100625105	4	LIGHT, UL 108" UNDERMOUNT SMOKE	6	2.00	55.30	110.60

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.60	185.00	111.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.80	185.00	148.00

Claim : 79038

```

*****
Lab Code Job# Description LABOUR Hrs Rate Total
*****

```

```

*****
Excode Job# Description EXTRAS Qty Price Total
*****
FRT 4 UPS-LIGHTS 1.00 16.30 16.30

```

```

Parts Total: 110.60
Labour Total: 259.00
Sublet Total: 0.00
Extras Total: 16.30

```

>>>> Claim Total: 385.90

Customer Signature: _____

Date: _____