



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79598
Promised Date:
26 APR 26



Customer #: 48072
CLARK, AMANDA



CUSTOMER WORK ORDER

WO #: 79598 (Appointment Date: 15 APR 2026 - Time: 04:00pm)

Customer: 48072 - CLARK, AMANDA -
307-630-7176

Tag:

Author: BJW

Location: 0417 CHECK PREAUTH

Stock #: 11575

Stock Desc: (11575) 2025 COACHMEN

CATALINA 343BHTSLE

Chassis #: 5ZT2CAZB8SX034724

Serial #: 5ZT2CAZB8SX034724

Mileage:

Licence:

Invoice #: 428783

Date In: 15 APR 26

Promised: 30 APR 26

Date Sched:

Completed: 16 APR 26

Warr. Date: 10 MAY 25

Job #1 - Warranty

COMPLAINT: 25V682, 2025-545 - MISSING OVERCURRENT PROTECTION

CAUSE: Recall

CORRECTION: Went to breaker and found it was wired incorrectly. Moved wires to correct position. Sprayed battery saver on terminals. Went inside and check 12v and 120 system to be working.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	39.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	7.61	7.61

Subtotal for Job #1: 46.61

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT WATER SQUIRTS OUT OF THE CITY WATER INLET WHEN THE PUMP IS ON AND UNIT IS RUNNING OFF OF FRESH TANK.

CAUSE: City inlet leaking

CORRECTION: Went to unit saw fresh tank was empty. Filled to 1/3 turned on pump and saw inlet was leaking. Removed inlet from unit by removing screws and foam. Took inlet off water line. Placed new inlet on and tightened down. Turned on pump to check to see if new inlet leaked. No leaks found. Placed putty on back of inlet and secured with screws. Silioched around inlet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
10-1105	62165 PW METAL MPT CITY WATER FLANGE	1.00	16.51	16.51

Subtotal for Job #2: 75.01

Job #3 - External

COMPLAINT: CUSTOMER ADVISES THAT THE STEPS WERE DRUG AND NOW THE DOOR CATCHES WHEN OPENING AND CLOSING.

CAUSE: Door dragging



CORRECTION: Brought unit in. Opened entry door. Did not feel door catching. Placed steps on ground. Saw were steps were damaged from dragging. Opened and closed entry door with steps down. Could not find door catching. Cannot replicate customer problem

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE CEILING IN THE OUTDOOR KITCHEN GETS LOOSE AND SAGS DOWN. SEE WRITER IF YOU HAVE QUESTIONS

CAUSE: Outside kitchen

CORRECTION: Brought unit in. Saw outside kitchen ceiling panel had pulled out of staples. Grabbed liquid nails and placed on 2x4 above panel. Stuck panel to liquid nails. Grabbed staple gun and shot staples into panel. Placed wood putty in old staple hole that ripped out and new holes. Cleaned up wood putty. Panel is back in place.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	39.00

Subtotal for Job #4: 39.00

Parts Total: 16.51
Labour Total: 136.50
Sublet Total: 0.00
Extras Total: 7.61
WORK ORDER TOTAL: 160.62

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Apr 2026

W/O: 79598
Promised Date: 30 APR 26



Customer #: 48072
CLARK, AMANDA

