

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2656407
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSSB0RG128014
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF265MLE
JULIAN PAUL SANCHEZ		DEALER RO #	73137
490 PECOS RIVER RD SW		CLAIM START DATE	04/28/2026
Los Lunas, NM 87031		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/15/2025	WARRANTY EXPIRATION DATE	05/15/2026

Claim Line Details

Labor

Line# 1

Operation Code

20-739-01-11-000637

Operational Description

Fan Motor - Exterior/Power Roof Vent (Ventline/Dexter)/Replace/Electrical

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-04-28 09:23:17 :: Complaint: Customer states rear vent lid will not open intermittently Cause: Gearbox is stripped, wall switch malfunction as well Correction: Replace motor/gearbox and replace wall switch.

Model#

Dlr Sub Hrs

1.00

Sub Labor Amt \$190.00

Serial#

Appr Hrs

1.00

Appr Labor Amt \$190.00

Notes

Claim submitted for warranty consideration. Will update when they respond.
OK, thank you.
Just waiting on a response from Dexter/ Ventline.
Nothing else needed at this time. Will update when they respond
Thank you.
Have you heard anything yet?
Authed to replace fan lift motor and gearbox, and wall switch.
VCB Dexter

Submitted	Labor Amt	\$190.00	Approved	Labor Amt	\$190.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$190.00		Total	\$190.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.