



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73237
Promised Date:
15 MAY 26



WO #: 73237

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9637 2026 LACROSSE
3411RK
Serial#: 5ZT2LCZB6TB012568
Chassis#: 5ZT2LCZB6TB012568
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 22 APR 26
Time In:

Job #1 - Warranty

COMPLAINT: BEDROOM DOOR FRAME IS WARPED

CAUSE: Bedroom door frame warped may be due to heat.
Unknown

CORRECTION: Door frame needs replacement.
to repair:
unscrew and peel the frame off.
reglue and add screws.
Cut door frame to size of 82"
Cut hole in door frame for striker plate
Piece needed is 82 " x 2 1/4 "
2.0hr. requested
Pictures attached

Customer #: 1000
MYERS "RV" CENTER,
INC.,



Labor

Job #	Description	Total
1	DOOR FRAME	N/C

Subtotal for Job #1: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 01 May 2026

Customer Signature : _____

Customer Work Order

W/O: 73237
Promised Date: 15 MAY 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

