



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73157
 Promised Date:
 02 MAY 26



WO #: 73157 (Appointment Date: 07 APR 2026 - Time: 08:15am)
 Customer Name: 59212 - ABRAHAMSON, ARTHUR ALLEN
 Completed Date: 02 MAY 26
 Invoice#: 310113
 Author: ADVISOR
 Stock Desc: 9517 2025 BAY STAR 3014
 Serial#: 142181
 Chassis#: 1F66F5DN8R0A02834
 Miles/Hrs: 7323
 Tag#: 7146
 Purchased Date: 18 APR 25
 Warranty Date: 18 APR 25
 Date In: 07 APR 26
 Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES SHADE OVER KITCHEN SINK FELL **NEED NUMBER OFF SHADE**

CAUSE: Unknown

CORRECTION: Pushed back up and it snapped into place. Juggled & wiggled it works as it should.
 Job Complete. Request .25

Labor

Job #	Description	Total
1	SHADE, EACH, R & R	46.25
Subtotal for Job #1:		46.25

Job #2 - External

COMPLAINT: CUSTOMER STATES LP MOUNTING CAME OFF BRACKET FROM UNDER UNIT

CAUSE: Hose loosed and dragged on the ground. Determined best place to mount with chris

CORRECTION: In search of bracket that will be best, found some nice brackets that will work good see picture bolted onto unit with locknut washers and regular washers and bolts. Did gas leak test no leaks.

Labor

Job #	Description	Total
2	LP MOUNTING BRACKET	N/C

Parts

Part #	Description	Qty	Price	Total
06-1430	LP LINE VALVE QUICK DISCONNECT	1.00	N/C	N/C
18598	3/8" X 3/8" FIP BRASS COUPLING	1.00	N/C	N/C
18599	3/8" MIP X 1/4" FIP BRASS BUSHING	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES IN FRONT OF SHOWER WHEN YOU STEP ON IT IT FEALS LIKE A SOFT SPOT

Customer #: 59212
 ABRAHAMSON, ARTHUR
 ALLEN





CAUSE: 1001 CUSTOMER REQUESTED That we check out a creaking sound that happens when you step in front of the shower

CORRECTION: The water heater needs to be removed to access underneath to add additional support bracing under the underlayment floor. Had to remove silicone and cut around hot water heater cover remove all bolts remove separating wall. Had to disconnect all waterlines, electrical connections gas lines and remove water heater from unit completely. I cut a 2 x 4 that wedges perfectly in between the floor and the black tank brace tightened up with some wedges went inside and removed vent underneath shower to access the floor under the shower .pre-drilled a couple holes and sent screws to tighten the floor To the bracing underneathIn regards.Jumped up and down on the floor did not hear no sounds got some silicone and sealed up my new brace in the outside and painted it black to match unit.to case number 1081466 3 hours have been approved.started the process to reinstall the water heater.Get water heater in place connect fall water lines put back up partition wall run gas line reconnect electrical.Installed outer panel scraped loose silicone recaulked with silicone around cover.Hooked up water to the unit to make sure that the water heater isnt leaking after the reinstallation. No drips from Connections behind water heater

Labor		
Job #	Description	Total
3	FLOORING	555.00
Subtotal for Job #3:		555.00

Job #4 - Warranty

COMPLAINT: CUSTOMER RECEIVED HOOD BRACKET BULLETIN

CAUSE: Recall hood brackets

CORRECTION: Got parts list for sevice Advisor.
 Job Complete

Labor		
Job #	Description	Total
4	BULLETIN - HOOD BRACKET	55.50

Parts				
Part #	Description	Qty	Price	Total
039707	LOCKNUT 10/24 NYLOCK 18-8	4.00	0.20	0.80
039708	WASHER FLAT 10SAE F/W 18-8	4.00	0.16	0.64
039709	PHILLIP PAN 10/24X1" 18-8	4.00	0.60	2.40
Subtotal for Job #4:				59.34

Parts Total:	3.84
Labour Total:	656.75
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	660.59

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.



Customer Signature : _____

Date: 02 May 2026

W/O: 73157
Promised Date: 05 MAY 26



Customer Work
Order

Customer #: 59212
ABRAHAMSON, ARTHUR
ALLEN

