

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2561546
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4FCRE26SS234418
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	020 / 020
Labor rate:	\$140.00	ITEM #	CRF29RL
OWNER INFORMATION		DEALER RO #	13195
THOMAS ZAGER		CLAIM START DATE	01/26/2026
8320 GROVE AVE		CLAIM END DATE	04/27/2026
Wisconsin Rapids, WI 54494			
USA			
Retail Date of Purchase	05/12/2025	WARRANTY EXPIRATION DATE	05/12/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-180-01-00-002172	Central Vacuum System (Read Notes!!!) - Appliances/Central Vacuum System/ Replace/No Tread Code		
Complaint, Cause, Correction				
Original Note : greeneway@dealer-advisors.com, 2026-01-26 12:57:03 :: Complaint: Vacuum in unit does not work. Customer tried charging but the unit doesn't work. Cause: Internal failure. Will not charge or turn on.				
Correction: Replace vacuum. Additional Note : greeneway@dealer-advisors.com, 2026-01-26 13:00:52 :: This is not a Dyson vacuum so not sure which labor code to choose.				
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt \$42.00
Serial#		Appr Hrs	0.00	Appr Labor Amt \$0.00
Notes				
REVIEWING				
AUTHORIZED PART ONLY				

Part

Line# 1	Item #	Description		
	F100448780	VACUUM, RECHARGEABLE, W/ACCESSORIES, WHITE AND BLACK, BUILT IN BATTERY [RACK 5] V#3140-1001		
	Model #	Serial #	Part tag	0000411462
	Sub Qty	Sub Dlr Price	Sub Freight	\$19.43
	Appr Qty	Appr Dlr Price	Appr Freight	\$19.43
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	30-92-01-00-001179	Pantry Latch - Interior/Interior Miscellaneous/Replace/No Tread Code		
Complaint, Cause, Correction				
Original Note : greeneway@dealer-advisors.com, 2026-01-26 13:02:15 :: Complaint: Pantry door holder is damaged. Will not keep pantry door closed. Cause: Latch is broken and no longer works. Correction: Replace latch Additional Note : greeneway@dealer-advisors.com, 2026-04-27 12:28:48 :: The latch ended up being okay, we needed to replace a screw with a longer screw.				
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$28.00
Notes				
PLEASE PROVIDE BETTER PHOTOS OF PART AND ISSUE				
Additional photos added. Thank you!				
AUTHORIZED				

Submitted	Labor Amt	\$112.00
	Parts & Freight	\$258.45
	Total	\$370.45

Approved	Labor Amt	\$28.00
	Parts & Freight	\$258.45
	Total	\$286.45

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	