



Warranty Claim Form

Date: 5/7/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE242XT3446433
Imagine 20BHA
Retail Purchase Date: null
Work Started: 4/17/2026
Work Completed: 4/17/2026

Claim Status: Paid
Dealer Work Order #: 13346B
Unit Offline Date: 3/5/2026

Claim #: 985001
Labor: \$98.00
Parts: \$4.90
Shipping: \$0.00
Total: \$102.90

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 660015 Passage Doors - Repair Door *Fault Code:* Damaged/Maintenance Casing

Problem: Top and bottom of the bathroom door have rough edges and missing finish.

Hours: .3

Cause: Unfinished wood on the door.

Amount: 42.00

Remedy: Used a marker to cover the edge on top and bottom of the door.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	2.10

Operation Line # 2

Flat Rate Code: 660002 Cabinet Doors - Repair Door

Fault Code: Damaged/Maintenance

Problem: The glass on the cabinet door above the stove has silicone smeared on it.

Hours: .2

Cause: Silicone from the manufacturer.

Amount: 28.00

Remedy: Used quick solve to clean it off.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.40

Operation Line # 3*Flat Rate Code:* 680048 Mattresses - R&R Mattress*Fault Code:* Damaged/Maintenance*Problem:* The main mattress has black marks on it.*Hours:* .2*Cause:* Stained from the manufacturer.*Amount:* 28.00*Remedy:* Cleaned off several spots on the main mattress, but one spot is still visible, but it looks much less so.*Sublet Repairs:* \$0.00*Manufacturer #:**Model #:**Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	1.40