

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13195

Date In:	26 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 26	Stock No:	11301
:	:	Year:	2025
Customer Name:	2773 - ZAGER, THOMAS	Manufacturer:	FOREST RIVER
Address:	8320 GROVE AVE	Brand:	CEDAR CREEK EXPERIENCE
:	WISCONSIN RAPIDS, WI	Model:	29RL
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	715-213-1606	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	TSZAG@WCTC.NET	Tag#:	DB;1/26 - apt: 4/10
Purchased Date:	30 APR 25	:	:
Delivery Date:	12 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4FCRE26SS234418	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - VACUUM IN UNIT DOES NOT WORK. CMR TRIED CHARGING BUT THE UNIT DOESN'T WORK.	W	1021 FORES
	CAUSE:	Damaged will not charge		
	CORRECTION:	Replace it with no one		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - PANTRY DOOR HOLDER IS DAMAGED. WILL NOT KEEP PANTRY DOOR CLOSED NOW.	W	1021 FORES
	CAUSE:	Damaged screw is ripped out of it		
	CORRECTION:	Replace it with longer screw open and close the door a few times and its now stain		
WARR	COMPLAINT:	Transferred to GRV*13195B on 22 APR 26 Estimate amount was 0.00 WARRANTY REPAIR 3 - SHOWER DOOR WILL NOT STAY LATCHED. USING A SCREW TO KEEP SHUT DURING TRAVEL TO NOT DAMAGE DOOR.	W	1020 GRAND
	CAUSE:	Shower door will not stay latched		
	CORRECTION:	Do tothe handle at the latched side being broken will need new shower door glass as the handle on other end is coming off too Its fixed and can be used		
1	COMPLAINT:	Transferred to GRV*13195B on 22 APR 26 Estimate amount was 0.00 DOUBLE CHECK UNIT FOR FOLLOWING TRIM- DINETTE HAD TRIM FALLING AND THE BATHROOM HAD SOME TRIM FALLING-	W	1021 FORES

Continued on page 2

Work Order : 13195

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
      CAUSE:      Check unit for falling trim and
                  delaminating
      CORRECTION: Found trim in bathroom shower and trim
                  around bathroom door is all fixed

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 82208780      VACUUM, RECHARCHABLE, W/ W-1021      1      239.02      239.02
WARR0 822051854      STRUT, COMPARTMENT/CABIN W-1021      0      5.85      0.00
WARR0 756815005210 2pk GAS SPRING MOUNTING W-1021      0      7.67      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JL      W-1021      0.50      140.00      70.00
ARR02 Z992      MISC LABOUR CODE (WARR JL      W-1021      0.15      140.00      21.00
ARR03 Z992      MISC LABOUR CODE (WARR JL      W-1020      0.00      140.00      0.00
      1 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR JL      W-1021      0.05      140.00      7.00
ARR03 Z992      MISC LABOUR CODE (WARR JL      W-1020      0.00      140.00      0.00
      1 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00
      1 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00
ARR03 Z992      MISC LABOUR CODE (WARR JL      W-1020      0.00      140.00      0.00
      1 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 FRT      FREIGHT      W-1021      1.00      19.43      19.43

```

```

*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      239.02      98.00      0.00      19.43      0.00      356.45
      Totals      239.02      98.00      0.00      19.43      0.00      356.45

```

&k2S
&k0S