

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12415

Date In:	21 JUL 25	Author:	MGRAY
Promised Date:	31 MAY 26	Stock No:	11048
:	:	Year:	2024
Customer Name:	16741 - JANECEK, DANI	Manufacturer:	FOREST RIVER
Address:	S1655 HEIDRICH RD	Brand:	FLAGSTAFF CLASSIC TT
:	LA VALLE, WI	Model:	832DBS
Postal/Zip:	53941	Miles/Hrs:	0
Phone#(res):	6084349662	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	PJANECEK@HOTMAIL.COM	Tag#:	SB: 4/4
Purchased Date:	05 OCT 24	:	:
Delivery Date:	18 APR 25	:	:
InService Date:	:	:	:
Serial#:	4X4TFLN22R1906059	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
SS      SEASONAL STORAGE                                E    16741  JANECEK
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF    E    16741  JANECEK
                   CONTAINED - TOWABLE
CAUSE:      Needed to be winterized and had an
            icemaker
CORRECTION:  Has now been winterized
1  COMPLAINT:  CUSTOMER STATES THAT THE FRONT DOOR        W    1021  FOREST
                   LOCK- THE TOP LOCK- IT IS VERY HARD TO
                   OPEN WITH THE KEY-
CAUSE:      The top lock is very hard to open
CORRECTION:  Top lock was very hard to open I sprayed
            it with silicone spray and then it was
            easy to open it is working like it
            should now   REQ: .20
2  COMPLAINT:  CUSTOMER STATES THAT THE AIR CONDIONERS- W    1021  FOREST
                   YOU CAN NOT TURN ON ZONE 2 BY ITSELF YOU
                   CAN ONLY TURN IT ON IF YOU ALSO HAVE
                   ZONE 1 ON
CAUSE:      Customer states that the air can not run
            zone 2 by itself without running zone 1
CORRECTION:  You have to go in the thermostat and
            change it in zone push system till you
            see zone 1 is off then you can run zone
            2   REQ: 30
3  COMPLAINT:  CUSTOMER STATES THAT THERE IS A SCREW ON W    1021  FOREST
                   THE TOP OF THE CAMPER, ABOVE THE ENTRY
                   DOOR- ON THE ROOF- IT SEEMS LIKE IT
                   WASNT SCREW IN ALL THE WAY-
```

Continued on page 2

Work Order : 12415

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      customer stated that there was  screw
                  pushing through the roof above the entry
      CORRECTION: was not able to find a screw abou NOTING
4      COMPLAINT:  CUSTOMER STATES THAT IN THE FRONT      W      1021      FORES
                  BEDROOM BY THE FRONT WINDOW IT LOOKS
                  LIKE THERE MAY HAVE BEEN A LEAK- THE
                  WALL PAPER IS CRINKLEY AND SEEMS LIKE IT
                  MAY BE COMING OFF-
      CAUSE:      Customer states that front window in
                  bedroom may have a leak the wall paper
                  is crinkling and seems to be coming off
      CORRECTION: At this time I dont think it was leaking
                  wall has a stress crack do not see any
                  water damage at this time  either  REQ:
                  .50

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON E-16741      0      9.62      0.00

```

```

*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY JL      E-16741      0.32      130.00      41.60
WS W495      WINTERIZE RV (WATER SY JL      E-16741      0.38      130.00      49.40
1 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.50      140.00      70.00
2 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.50      140.00      70.00
3 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00
4 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.00      140.00      0.00
4 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.11      140.00      15.40
4 WARR      MANUFACTURER WARRANTY      JL      W-1021      0.39      140.00      54.60

```

```

*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
SS  SS      SEASONAL STORAGE      E-16741      0.00      0.00      0.00
SS  SSE      SHOP SUPPLIES - EXTERNAL      E-16741      1.00      6.83      6.83
SS  J-ADJ      QUOTE ADJUSTMENT      E-16741      1.00      200.17      200.17
WS  J-ADJ      QUOTE ADJUSTMENT      E-16741      1.00      14.00      14.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      16741      0.00      91.00      0.00      221.00      17.19      329.19
W      1021      0.00      210.00      0.00      0.00      0.00      210.00

```

Continued on page 3

Work Order : 12415

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	301.00	0.00	221.00	17.19	539.19

&k2S
&k0S