

Warranty Claim Detail

R.O. Number **73037**
 Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	0435
Description	Paint-Newmar-Slideout, Wall complete
Occurrences	1
Requested Hours	.00
Authorized Hours	.00
Fault Code	12-Cracked
Vendor Responsible	800000-CUSTOMER PAY Hours:.00

GENERAL INFORMATION	
Status	Denied
Denial Code	14-Unit is out of warranty
Date In	03/16/2026
Submit Date	03/17/2026
Authorization	No 03/17/2026
Work Complete	No
Payment	No

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/17/2026 AT 10:03 AM BY DEALER This was originally approved under work order 71281. Customer had trips planned and could not stay for the paint repair. Emailed copy over for sublet estimate and screens hot of previous approval with sublet of \$971.06 in sublet field.

TOTALS	Requested	Authorized
Labor	.00	.00
Sublet	971.06	.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	971.06	.00
TOTAL PAID		.00

AUTHORIZATION NOTES
COMMENT ENTERED ON 03/17/2026 AT 10:22:17 AM BY ALDUNNING CASE 01073222 COMMENT ENTERED ON 03/17/2026 AT 11:41:45 AM BY PKING ===== ITS BEEN A YEART SENSE THIS WAS APPROVED. TIME HAS EXPIRED ON THIS

DEALER CORRECTION
COMMENT ENTERED ON 03/17/2026 AT 10:03 AM BY DEALER Sublet for paint repair.

