

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2615293 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2AVEC2TG815607 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 452 / 452 <b>ITEM #</b> AVT16RBX-452 <b>DEALER RO #</b> 72857-1 <b>CLAIM START DATE</b> 03/20/2026 <b>CLAIM END DATE</b> 01/01/1900
--	--

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code** 20-43-01-00-000589      **Operational Description** Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-03-20 08:58:03 :: Complaint: Right side decal is torn Cause: Torn decal Correction: Replace decal

<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.50	<b>Sub Labor Amt</b> \$95.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.50	<b>Appr Labor Amt</b> \$95.00

**Notes**  
 NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

### Labor

**Line# 2**      **Operation Code** 20-46-01-00-000731      **Operational Description** Window Latches - Exterior/Windows/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-03-20 08:59:13 :: Complaint: Driver side emergency exit window latch is broken Cause: Plastic end broke off Correction: Replace handle and arm

<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20	<b>Sub Labor Amt</b> \$38.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20	<b>Appr Labor Amt</b> \$38.00

**Notes**

<b>Submitted</b>	Labor Amt	\$133.00	<b>Approved</b>	Labor Amt	\$133.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$133.00		Total	\$133.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.