



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27141



WO #: 27141

Customer: 93533 - HUSKINS, JEREMIAH  
Address: 716 BRYANT TERRACE  
POWELL, TN  
37849  
Home Phone: (423) 220-6928  
Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11043  
Stock Desc: 2025 TT KZ-RV SPORTSMEN SE  
301DBSE  
Model: 301DBSE  
Serial #: 4EZTU3028S5107466  
Chassis #:  
Mileage:  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date: 19 DEC 25  
Date In: 11 MAY 26  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date: 19 DEC 25

**Job #1 - Warranty**

COMPLAINT: CUST COMPLAINED ABOUT WATER LEAKING OUT OF THE CORNER OF THE SHOWER WHEN USING IT

CAUSE: TECH CHECKED ALL FITTINGS AND DRAIN PIPES, NO LEAKS. VERIFIED WATER IS POOLING UNDERNEATH CORNER OF SHOWER DUE TO THE GAP BETWEEN SHOWER PAN AND WALL.

CORRECTION: NEED TO APPLY SEALANT TO GAP TO PREVENT WATER FROM LEAKING ONTO THE FLOOR WHEN CUSTOMER IS USING THE SHOWER  
LABOR .40

**Subtotal for Job #1: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93533  
HUSKINS, JEREMIAH



Customer Signature : \_\_\_\_\_

Date: 11 May 2026

