



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 63532
Promised Date: 17 MAR 21

CUSTOMER WORK ORDER

WO #: 63532

Customer: 50919 - EWELL, KEVIN -
618-922-3274

Tag:

Author: BH

Location: DELIVERY

Stock #: 10512

Stock Desc: 2020 5W KEYSTONE
MONTANA 3781RL

Chassis #: 4YDF37829L4702716

Serial #: 4YDF37829L4702716

Mileage:

Licence:

Invoice #:

Date In: 05 MAR 21

Promised: 17 MAR 21

Date Sched:

Completed: 29 MAR 21

Warr. Date: 24 FEB 21

Job #10 - Warranty

COMPLAINT: THE SEAL AROUND THE LEFT FRONT STORAGE
AREA IS COMING DOWN.

CORRECTION: check with parts, oRder seal, close up unit and pull out and park on lot

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	42.90
Z990	MISCELLANEOUS REPAIR	JP	85.80

Parts

Part #	Description	Qty	Price	Total
219210	TRAPEZOID SEAL	16.00	0.29	4.64

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAL	1.00	11.99	11.99

Subtotal for Job #10: 145.33

Job #1 - Internal

COMPLAINT: INSTALL LOCKOUT KIT

CAUSE: PREBILLED TO JP
PARTS ON RO 63469

CORRECTION: INSTALL LOCK OUT KIT AND CLOSE UP UNIT AND PULL OUT AND PARK ON LOT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: INSTALL 2 1WAY CARGO SLIDES

CAUSE: PREBILLED TO JP
PARTS ON 63469

CORRECTION: pull down underbelly to find black and gray tanks, tanks are under tray compartment
suplied screws are too long will go into tanks, have to cut 3/4 in boards to raze traya to come out over door

Customer #: 50919
EWELL, KEVIN



frame, use 1 1/2 in screws to fasen down and not go in to tanks

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: WALK

CAUSE: PREBILLED TO EF

CORRECTION: DONE EF

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	EF	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	EF	N/C

Subtotal for Job #3: 0.00

Parts Total: 4.64
Labour Total: 128.70
Sublet Total: 0.00
Extras Total: 11.99
WORK ORDER TOTAL: 145.33

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Jul 2021

W/O: 63533
Promised Date: 17 MAR 21



Customer #: 50919
EWELL, KEVIN



Pre-Authorization

Pre-Authorization number PA02785405 Reference no: 63532 Status: Approved Approved by perry Approved date 3/29/2021
Technician Name Address VIN Retail sold on

94 Basden's American RV Basden's American RV 4YDF37829L4702716
600 E Baseline Rd
Evansville, IN 47725

Item	Root Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2302414B Compartment Doc	0.00	1.00	0.50		1	0.20	Complaint: THE SEAL AROUND THE LEFT FRONT STORAGE AREA IS COMING DOWN Cause: LOOK AT SEAL IS COMING DOWN BECAUSE IS NOT STICKING TO THE FRAME OF THE UNIT Correction: NEED TO PULL SEAL OFF AND CLEAN THE AREA AND INSTALL NEW SEAL ON THE DOOR

Pre-Authorization number PA02785405 0.50

This paper claims only use one pre-authorization number per warranty claim for
Please a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the