

Tag Number: _____

Estimate No. **1376**

Estimate Date: May 8 26



Customer: Myers Rv Center

12024 Central Av SE

Albuquerque NM 87123

International Motor

Make: MV Ghost

Model: MV6078BA

Year: 2025

VIN: 1HTEUNML1T8217297

Oxidation RV Repair Service

4516 2nd St NW

Albuquerque, NM 87107

505-417-9386

oxidationrv@gmail.com

Estimate	Amount
Repair Crack on Driverside Door Top Wall Corner	
Repair with Resin/mat	
" " Fiberglass 3.0	
" " putty	
Prime	1.5
Paint 2 colors Silver / Dark Gray	
Paint panel Clear 3.0	
Color sand Buff Sanded Hand Glove	
1.5	
8.0 77 hr	
per hr 45 point material	
Paint Mix	\$ 360.00
Waste Disposal	10.00
Shop Supplies	15.00
Labor	616
Parts	
Misc.	
Subtotal	7001
Sales Tax	
Total	\$ 7001.00

Adjuster Name: _____

Claim Number: _____

Telephone No. _____

Customer Signature: B

Date: _____