



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64194
Promised Date: 30 JUN 21

CUSTOMER WORK ORDER

WO #: 64194

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:

Author: BH

Location: DELIVERY 0601

Stock #: 10923

Stock Desc: 2022 C COACHMEN
FREELANDER 27QB

Chassis #: 1FDWE3FN9MDC39007

Serial #: 1FDWE3FN9MDC39007

Mileage: 0

Licence:

Invoice #: 362382

Date In: 13 MAY 21

Promised: 30 JUN 21

Date Sched:

Completed: 30 MAY 21

Warr. Date: 04 JUN 21

Job #PDINMHC - External

COMPLAINT: PDI - NEW MOTORHOME "C"

CAUSE: PDINMHC - PDI NEW MOTORHOME "C"

CORRECTION: Filled LP tank. Moved unit into shop from rental lot. Removed all wheel liners. Checked lug nuts and set tire pressures. Checked all engine fluids. Checked all exterior lights. Checked entrance door and all compartment doors. Checked roof and awning. Checked power cord. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked TV Antenna, TV and Radio. Checked all appliances. Checked converter output. Filled fresh water tank. Flushed antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from water system. Performed LP drop test and set LP pressure at 11 in.wc. Filled all holding tanks and checked monitor panel.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
17-1917	8009 VALVE STEM EX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	16.10	N/C	N/C

Subtotal for Job #PDINMHC: 0.00

Job #FPDINMHC - External

COMPLAINT: FINAL PDI ON NEW MOTORHOME CLASS C

CAUSE: FPDINMHC - FINAL PDI ON NEW MOTOR HOME CLASS C.

CORRECTION: Dumped all holding tanks. Applied all company decals. Removed "Winterized" label. Recorded all serial numbers and took pictures. Recorded all tire serial numbers. Moved unit to rental lot.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 46875
CHUBBY CHOW FACTORY

PDINMHC	PDI - NEW MOTORHOME "C"	DKM	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	DKM	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	DKM	N/C
PDINMHC	PDI - NEW MOTORHOME "C"	DKM	N/C

Subtotal for Job #FPDINMHC: 0.00

Job #MAXX - External

ROOF VENT COVER - INSTALLED EACH

Labor Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	DKM	N/C

Parts Part #	Description	Qty	Price	Total
40431	CAMCO VENT COVER -	4.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #1 - External

INSTALL VALVE STEM EXTENDERS

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BLACK TANK NOT READING CORRECT ON THE MONITOR

CAUSE: BLACK TANK NOT READING CORRECTLY ON MONITOR PANEL.

CORRECTION: Monitor panel reads empty no matter how much water is in tank. Checked all wiresconnected to black tank. Ground wire connected to ground probe on tank not good. Ran a new ground wire from frame to ground probe on tnk. Monitor now read correct for amount of water in tank.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	65.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	130.00

Subtotal for Job #2: 195.00

Parts Total:	0.00
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 195.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 64194
Promised Date: 30 JUN 21



Customer #: 46875
CHUBBY CHOW FACTORY



Customer Signature : _____

Date: 04 Jun 2021

W/O: 64194
Promised Date: 30 JUN 21



Customer #: 46875
CHUBBY CHOW FACTORY



Customer Work
Order



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD

EVANSVILLE, IN 47725
USA

Labor rate: \$130.00
OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 628242
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZTCFLS09NW427979
CHASSIS VIN 1FDWE3FN9MDC39007
MILEAGE 345
SITE/WAREHOUSE 210 / 210
ITEM # FLC27QBF35
DEALER RO # 64197
CLAIM START DATE 06/02/2021
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1 Operation Code Operational Description
40-112-24-11-001350 Monitor Panel Wiring or Harness - Electrical/Monitor Panel/Repair/
Electrical
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2021-06-02 14:16:37 :: BLACK TANK NOT READING
CORRECT ON THE MONITOR BLACK TANK NOT READING CORRECTLY ON MONITOR PANEL. Monitor
panel reads empty no matter how much water is in tank. Checked all wires connected to black tank. Ground
wire connected to ground probe on tank not good. Ran a new ground wire from frame to ground probe on
tank. Monitor now read correct for amount of water in tank.
Model # Dlr Sub Hrs 1.50 Sub Labor Amt \$195.00
Serial # Appr Hrs 1.50 Appr Labor Amt \$195.00
Notes
jj

Submitted	Labor Amt	\$195.00	Approved	Labor Amt	\$195.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$195.00		Total	\$195.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.