

Nexus Dealer

Phone: Phone:
b.parrott@myersrv.com;Rhianna.s@myersrv.com
Date of Purchase:
Year: 2026 Make: Ghost Model: 38DS
VIN: 1HTEUMML1TS217297

AUTHORIZATION #: 17721
Nexus RV Serial Number: 18780
Work/Repair Order: 73271Sublet
Service In Date: 04/27/2026
Service End Date:
Mileage: 1,679.00
Bill Ref #: 17721
Bill Ref # Date:
Date: 05/12/2026 Created By: Christy

Estimate Prepared For Customer:

Status: Authorization
Approved

Estimate Prepared For Service Location: 98001

Myers RV Center
12024 Central Ave SE

Albuquerque NM, 87123

	Item Code	Description	Complaint	Cause	Correction	Rate	Qty	Amt	Nexus Hrs	Nexus Amt
	1 1	estimate	This is the sublet that was on PA 17690 for the crack on driverside door	Sublet for repair to crack in door	Repair with resin, fiber glass and putty, prime and paint 2 colors silver and dark gray, paint panel clear, color sand buff	1,001.00	1.00	1,001.00	1.00	1,001.00
									Requested \$1,001.00	Authorized \$1,001.00

Comments:

Nexus Subtotal: \$1,001.00
Sales Tax: \$0.00
Total: \$1,001.00