

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	1054928	CLAIM STATUS	Paid
LINK FORD & RV MINONG LLC		CLAIM	2663076
1025 W HOKAH ST		CLAIM ORIGIN	WEB
MINONG, WI 54859		ORIGINAL CLAIM ID	
USA		VIN	4X4TSML21GM024302
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	004 / 004B
OWNER INFORMATION		ITEM #	SMT353FLFB
JEFFREY PLASCH		DEALER RO #	40464
940 MONTEREY CT S		CLAIM START DATE	05/04/2026
Shoreview, MN 55126		CLAIM END DATE	05/06/2026
USA			
Retail Date of Purchase	10/01/2016	WARRANTY EXPIRATION DATE	10/01/2017

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	RC-003-13-00-004757	25V682, 2025-545 - MISSING OVERCURRENT PROTECTION - INSPECT & REPAIR - Recall/Electrical/Relocate/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : alix@dealer-advisors.com, 2026-05-04 11:59:30 :: Complaint: Customer states 12-volt recall - 30amp is hooked to constant 12volt power. Cause: Hooked up to constant power side of relays. Correction: Looked on the frame and found they had the wires hooked to the constant power side of the relays on the frame so I took both wires off and put them on the other side of the relays so they are protected now.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$49.50
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$33.00
	Notes			
	Authorized			
	.20 per service campaign, requesting more time please add a new line using the same repair code			

Submitted	Labor Amt	\$49.50	Approved	Labor Amt	\$33.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$49.50		Total	\$33.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.