

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2632797  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TPUP2XTP108817  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 420 / 420  
 ITEM # PUT38RLB  
 DEALER RO # 13262B  
 CLAIM START DATE 04/07/2026  
 CLAIM END DATE 04/24/2026

Labor rate: \$140.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 50-134-01-00-001443      LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

**Complaint, Cause, Correction**

Original Note : greeneway@dealer-advisors.com, 2026-04-07 07:53:02 :: Complaint: LP regulator is defective.  
 Cause: The LP regulator was defective, did a manometer test at the front LP quick connect and it was reading in the 20s. Correction: Replaced it with a new LP regulator.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$140.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$70.00

**Notes**

pending part return  
 Part Return Required. Please attach tracking information. Part will be processed when received.  
 Please leave on your side.

1Z03RW629015433175  
 Thank you for the tracking information. Claim will be processed once part is received. Please leave on your side

### Part

Line# 1	<b>Item #</b>	<b>Description</b>			
	50G01933A	REGULATOR, CAVAGNA AUTO LP WITH L BRACKET, TRAVEL TRAILER REGULATOR, CAVAGNA AUTO LP WITH L BRACKET, TRAVEL TRAILER			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>	0000411677	
	Sub Qty	1.00	Sub Dlr Price	\$94.39	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$41.55	Appr Freight \$0.00

**Notes**

Total part cost equals Dealer/Standard price \$31.96 (Vendor Price \$19.93 + 65% FR parts mark up) + 30% state mark up

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 30-99-24-00-001030      Valance - Interior/Soft Goods/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2026-04-07 07:54:11 :: Complaint: The valance on the DS in the main bedroom has scratches in the fabric. Cause: There is a couple scratched on the fabric on the DS valance in the main bedroom. They are very hard to see with natural light. Correction: Noting. Nothing being done at this time.

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt \$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00

**Notes**

---

<b>Submitted</b>	Labor Amt	\$140.00
	Parts & Freight	\$72.61
	Total	\$212.61

<b>Approved</b>	Labor Amt	\$70.00
	Parts & Freight	\$41.55
	Total	\$111.55

---

<b>DEALER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

I certify that I have performed these repairs consistent with Forest River Policies.

---

<b>CUSTOMER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

All repairs described have been inspected and are satisfactory.