



Warranty Claim Form

Date: 5/18/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2926R3439562

Imagine 24BSE

Retail Purchase Date: 4/21/2026

Work Started: 4/27/2026

Work Completed: 5/7/2026

Claim Status: Paid

Dealer Work Order #: 13413

Unit Offline Date: 5/15/2024

Claim #: 986603

Labor: \$42.00

Parts: \$69.37

Shipping: \$198.03

Total: \$317.40

Notes: Sg 4/28/26 *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 640017 Trims/Fascia - R&R Decorative Fascia *Fault Code:* Improper Installation/Build Boards (ea)

Problem: The bedroom slide arm has a chunk of wood missing from the backside of it.

Hours: .3

Cause: I touched it up to the best of my ability in case customer does not want to wait for the part to come before taking his unit.

Amount: 42.00

Remedy: R&R fascia - 6" wide by 55" tall with small black plastic strip imbedded in it.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
640837 FASCIA 1/2 X 6 X 144 MOBSTER MAPLE 3D LEG W/MATTE BLACK STRIP	FASCIA 1/2 X 6 X 144 MOBSTER MAPLE 3D LEG W/MATTE BLACK STRIP		1	1	69.37

Operation Line # 2

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified Fee

Problem: Invoice 1572832

Hours: 0

Cause: Invoice 1572832

Amount: 0.00

Remedy: Invoice 1572832

Sublet Repairs: \$8.00

Manufacturer #:

Model #:

Serial #: