

# DAF: Dealer Unit Inspection Form



FOREST RIVER

Forest River, Inc.  
66149 SR 19  
Wakarusa, IN 46573  
USA

Short VIN/Unit: AVB942415

Model/Item: AVT25RBS

Dealer: LINK FORD & RV MINON

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

|                 |                                      |    |
|-----------------|--------------------------------------|----|
| Keys            | <input checked="" type="radio"/> Yes | No |
| BBQ Grill       | <input checked="" type="radio"/> Yes | No |
| Power Cord      | <input checked="" type="radio"/> Yes | No |
| Warranty Packet | <input checked="" type="radio"/> Yes | No |
| Sink cover      | <input checked="" type="radio"/> Yes | No |
| Jack Handles    | <input checked="" type="radio"/> Yes | No |
| TV 1            | <input checked="" type="radio"/> Yes | No |
| TV 2            | <input checked="" type="radio"/> Yes | No |
| Remotes         | <input checked="" type="radio"/> Yes | No |

List Any Miscellaneous Comments Regarding Condition of Unit:

List Any Additional Missing Items:

| Suggested areas to inspect: |                                                                                                                                                                             |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Unit Cleanliness            | If no, explain:                                                                                                                                                             |
| Condition of Flooring       |                                                                                                                                                                             |
| Cabinetry Damage            | If yes, explain:                                                                                                                                                            |
| Appliance Condition         |                                                                                                                                                                             |
| Furniture Tears/Stains      | If yes, explain:                                                                                                                                                            |
| Frame/Chassis Condition     |                                                                                                                                                                             |
| Roof Components             |                                                                                                                                                                             |
| Roof Material               | rear corners have bunched up material                                                                                                                                       |
| Awning Fabric               |                                                                                                                                                                             |
| ODS/DS Walls & Graphics     |                                                                                                                                                                             |
| Unit Front & Graphics       |                                                                                                                                                                             |
| Unit Rear & Graphics        |                                                                                                                                                                             |
| Additional Notations        | - Reseal roof inspts.<br>- Screen door of main door doesn't open properly.<br>- 1st ceiling panel in bedroom has scrape.<br>- Fascia from left side of slide-out has a gap. |

Unit/Underside has been washed by the Dealership

Yes

No

Date Washed

5/13/26

Dealer Signature

*Bonnie Freeman*

Date

5/13/26