



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27172



WO #: 27172

Customer: 93152 - CULBERTSON, ROBERT
Address: PO BOX 262
NORTON VA
24273
Home Phone: (276) 219-9555
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11126
Stock Desc: 2025 TT KZ-RV CONNECT SE
211MKSE
Model: 211MKSE
Serial #: 4EZTL2320S4046550
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 28 APR 26
Date In: 16 MAY 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 28 APR 26

Job #1 - Warranty

COMPLAINT: LEFT SIDE OF SOFA SECTION - FOOT REST HITTING BOTTOM BRACE

CAUSE: BOTTOM BRACE IS TOO CLOSE TO THE BASE

CORRECTION: NEED TO ADD WASHER TO RAISE OFF THE BASE
LABOR .40

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LEFT SIDE OF SOFA SECTION MASSAGE WAS NOT WORKING, TECH FOUND WIRES WERE DISCONNECTED. AFTER CONNECTING THESE WIRES THE MASSAGE WORKS HOWEVER, THE CUP HOLDER LIGHT WILL NOT TURN OFF NOW.

CAUSE: WIRING ISSUES ON LEFT SIDE OF SOFA SECTION SEATING

CORRECTION: REPLACE SEATING ON LEFT SIDE OF SOFA
LABOR .50

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 16 May 2026

Customer #: 93152
CULBERTSON, ROBERT

