

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2642197  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2AVSB2TB941118  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 050 / 050  
 ITEM # AVT27REI  
 DEALER RO # 73163  
 CLAIM START DATE 04/14/2026  
 CLAIM END DATE 05/14/2026

Labor rate: \$190.00

OWNER INFORMATION  
 ANGEL MARQUEZ  
 9125 COPPER AVE NE #622  
 Albuquerque, NM 87123  
 USA

Retail Date of Purchase 04/11/2026      WARRANTY EXPIRATION DATE 04/11/2027

## Claim Line Details

### Labor

Line# 1	<b>Operation Code</b> 20-57-24-00-000605 <b>Complaint, Cause, Correction</b> Original Note : stephanie@dealer-advisors.com, 2026-04-14 19:45:58 :: Complaint: Front cap trim is loose on passenger side Cause: Not secure Correction: rescore trim	<b>Operational Description</b> Loose Moldings - Exterior/Exterior Fiberglass Walls/Repair/No Tread Code
Model#	Dlr Sub Hrs 0.25	Sub Labor Amt \$47.50
Serial#	Appr Hrs 0.20	Appr Labor Amt \$38.00
<b>Notes</b> Authed for flat rate		

<b>Submitted</b>	Labor Amt	\$47.50
	Parts & Freight	\$0.00
	<b>Total</b>	<b>\$47.50</b>

<b>Approved</b>	Labor Amt	\$38.00
	Parts & Freight	\$0.00
	<b>Total</b>	<b>\$38.00</b>

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 All repairs described have been inspected and are satisfactory.