



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64605
Promised Date: 31 JUL 21

CUSTOMER WORK ORDER

WO #: 64605

Customer: 39485 - BROWN, TIMOTHY E.
- 812-629-0002

Tag:

Author: BH

Location: 0715 CUSTOMER HAS TO
HAVE UNIT BACK

Stock #: 10601

Stock Desc: 2021 TT COACHMEN
CATALINA 343BHTSLE

Chassis #: 5ZT2CAZB0MX022411

Serial #: 5ZT2CAZB0MX022411

Mileage: 0

Licence:

Invoice #:

Date In: 01 JUL 21

Promised: 31 JUL 21

Date Sched:

Completed: 07 JUL 21

Warr. Date: 21 MAY 21

Job #1 - Warranty

COMPLAINT: THE CEILING PANEL ABOVE THE SHOWER NEAR THE SKYLIGHT IS CRACKED AND NEEDS REPLACED

CORRECTION: REMOVED SKYLIGHT. REMOVE BATON STRIP ON CEILING. CUT OUT DAMAGED CEILING PANEL. SHIM UP CEILING JOIST THAT WAS TOO HIGH. TOOK PICS. PUT BLOCKING IN WHERE NEEDED. INSTALL NEW CEILING PANEL. PUT ON NEW BATON ON WALL AND CEILING. SILICONED EDGES. PUT BACK SKYLIGHT. . PUTTY HOLES.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	390.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Parts

Part #	Description	Qty	Price	Total
C01226181	PANEL, CEILING, 2.	32.00	0.79	25.28
500627	SILICONE - N PLUS	1.00	7.57	7.57

Other Services

Code	Description	Qty	Price	Total
FRT	CRATE FEE	1.00	45.00	45.00
FRT	FREIGHT - JOBS 1,2	1.00	82.02	82.02

Subtotal for Job #1: 549.87

Job #2 - Internal

COMPLAINT: VALANCE ABOVE THE COUCH IS FALLING DOWN

CORRECTION: TOOK PICS. SCREWED BACK VALANCE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #2: 0.00

Customer #: 39485
BROWN, TIMOTHY E.



W/O: 64605
Promised Date: 31 JUL 21

Parts Total:	32.85
Labour Total:	390.00
Sublet Total:	0.00
Extras Total:	127.02
WORK ORDER TOTAL:	549.87

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 07 Jul 2021

Customer Work
Order



Customer #: 39485
BROWN, TIMOTHY E.

