



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79652



Customer #: 56540
FISCHER, SARAH



CUSTOMER WORK ORDER

WO #: 79652

Customer: 56540 - FISCHER, SARAH -
812-550-5670

Tag:

Author: BH

Location: 0511 CHECK WORK

Stock #: 11559

Stock Desc: 2025 TT COACHMEN
FREEDOM EXPRESS 21SE

Chassis #: 5ZT2FEKB7SW030811

Serial #: 5ZT2FEKB7SW030811

Mileage:

Licence:

Invoice #:

Date In: 21 APR 26

Promised:

Date Sched:

Completed: 07 MAY 26

Warr. Date: 06 MAR 26

Job #1 - Warranty

COMPLAINT: THE ANTENNA CORD BROKE AND DETACHED FROM THE TV

CAUSE: Coax cable broke

CORRECTION: Took off broken cable and replaced it with a new one. I put new ends on the cable

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	39.00

Subtotal for Job #1: 39.00

Job #2 - Warranty

COMPLAINT: Light over sink flickers - could be a loose led?

CAUSE: Light over sink flickers

CORRECTION: So i took the light out and took off the connectors and checked the wires. I stripped two of the wires a little bit more and put new connectors on. But the longer you leave the light on it starts to flicker. I checked the voltage and it was good at the light. So i put in a parts request for a new light

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
13070	LIGHT, RV LED WAFER SLIM W/DIMMABLE	1.00	8.78	8.78

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	16.77	16.77

Subtotal for Job #2: 84.05

Job #3 - Warranty

COMPLAINT: Outdoor sink cold line leaks underneath and it drips fairly often from the faucet - tried tightening but I think there's a plastic piece that was broken.

CAUSE: Outdoor kitchen cold line leaks



CORRECTION: I pressurize the system and seen the cold line drip. So i took it apart and the fitting may have a crank. So i replaced the fitting and i cut some off the hose to make a good seal. And tested it on pump and city no leaks

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	39.00

Parts Part #	Description	Qty	Price	Total
681487	1/2" BARB X 1/2 FPT SWIVEL CONE	1.00	2.24	2.24

Subtotal for Job #3: 41.24

Job #4 - Warranty

COMPLAINT: Outdoor sink water drain line leaks at white joint coupler - tried tightening but it was still leaking.

CAUSE: Outdoor kitchen drain leaks

CORRECTION: Pressurized system and ran water through the drain and i seen it leak. So i went ahead and took the drain apart and made sure the rubber hose was pushed up were it needed to be and put some dope on the threads and made sure it screwed on properly and tightened the joint and checked it again for leaks. And no leaks. I tested it on pump and city water pressure

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	58.50

Subtotal for Job #4: 58.50

Job #5 - Warranty

When we put out the awning, I think there's a hole in the awning over the kitchen.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: THE OUTDOOR KITCHEN DOES NOT LOCK

CAUSE: Outdoor kitchen door hard to lock.

CORRECTION: After inspection of the door lock and you had to push in on the door. I changed the lock blade and it locks easily now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	19.50

Subtotal for Job #6: 19.50

Job #7 - Warranty

COMPLAINT: INSIDE KITCHEN FAUCET IS LEAKING ON THE HOT SIDE

CAUSE: Hot water line under kitchen sink leaks

CORRECTION: When i was hooked up to city water working on the outdoor kitchen leak that the hot line was leaking. So i took it apart and seen the from the factory the cone washer was installed incorrectly. So i put a. Ew cone washer in and pressurized the system and no leaks.

Labor Code	Description	Mechanic	Total
------------	-------------	----------	-------



Parts				
Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL SEAL	1.00	0.31	0.31
Subtotal for Job #7:				39.31

Parts Total: 11.33
Labour Total: 253.50
Sublet Total: 0.00
Extras Total: 16.77
WORK ORDER TOTAL: 281.60

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 07 May 2026

Customer Signature : _____

W/O: 79652



Customer #: 56540
FISCHER, SARAH

