



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79711



CUSTOMER WORK ORDER

WO #: 79711 (Appointment Date: 23 APR 2026 - Time: 10:00am)

Customer: 50939 - ALVEY, GREGORY -
270-993-1229

Tag:

Author: BH

Location: 0430 CHECK PREAUTH

Stock #: 11530

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 324RLDS

Chassis #: 5ZT2FEXB6SW030243

Serial #: 5ZT2FEXB6SW030243

Mileage:

Licence:

Invoice #:

Date In: 25 APR 26

Promised:

Date Sched:

Completed: 30 APR 26

Warr. Date: 09 MAR 26

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT EVERY NOW AND THEN A CODE WILL COME UP ON THE REFRIGERATOR. CUSTOMER TOOK UNIT TO GULF SHORES AND THE REFRIGERATOR COOLED, BUT SOMETIMES IT WOULD HAVE A CODE AND SOMETIMES IT WOULD NOT. WHEN IT WOULD GET A CODE, CUSTOMER COULD SHUT THE REFRIGERATOR DOOR A LITTLE HARDER AND THE CODE WOULD GO AWAY. SOMETIMES THE DOOR WILL OPEN AND THE LIGHT WILL NOT COME ON THE FRIDGE IS ASKING LIKE IT HAS A MIND OF ITS OWN--- THE FRIDGE SOMETIMES MAKES A ALARM NOISE AND YOU HAVE TO PUSH OR HIT IT AND THE ALARM GOES OFF THE CODE THAT IT SHOWS IS AN E03 CODE

CAUSE: Door buttons

CORRECTION: Plugged in the shore power then opened the sliderooms to get to the fridge. Reviewed the job line notes and inspected the fridge door. Found there was shims on the top of the door on the left side but not the rights side. Found the left side that has the shims, the button was being triggered easily but not the right. Pulled off the shims on the left side and split the shims then put more double sided tape to thicken the shims and push the button in further. Took pictures of the process. After the shims fix checked the door buttons and the left side didn't trigger causing the E0 error code. Closed the sliderooms.

Customer #: 50939
ALVEY, GREGORY



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	195.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 195.00

Parts Total: 0.00
 Labour Total: 195.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 195.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

