

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2669340
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCFLS03TP432862
USA		CHASSIS VIN	1FDWE3FN7SDD30130
		MILEAGE	5694
		SITE/WAREHOUSE	210 / 210
		ITEM #	FLC27QBF35
		DEALER RO #	79842
		CLAIM START DATE	05/08/2026
		CLAIM END DATE	01/01/1900
Labor rate:	\$195.00		
OWNER INFORMATION			
CHUBBY CHOW FACTORY LLC FACTORY LLC			
PO BOX 3641			
Evansville, IN 47715			
USA			
Retail Date of Purchase	05/07/2025	WARRANTY EXPIRATION DATE	05/07/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-78-02-00-000797	Lippert Awning - complete - Exterior/Awnings (Lippert)/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-08 11:28:21 :: AWNING IS GRINDING INTERMITENTLY AT A CERTAIN SPOT ROLLING IN AND OUT. Pulled unit into shop. Ran awning in and out several times. Removed the awning covers and inspected the roller tube and posts. Nothing seems bent or damaged. Lubricated with wd40 and it got louder. 3 in 1 oil may help but we don't have any. Asking oarts to go get some in the morning. Spoke with Todd. I will close the work order. When the oil arrives I'll apply it to the awning and install the covers.B			
	Model# NA	Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
	Serial# NA	Appr Hrs	0.00	Appr Labor Amt \$0.00
	Notes			
	Forest River does not warrant lubrication.			

Labor

Line# 2	Operation Code 20-739-01-00-000640	Operational Description Interior Vent Garnish - Exterior/Power Roof Vent (Ventline/Dexter)/Replace/No Tread Code		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2026-05-08 11:42:28 :: VENT ABOVE BUNK HAS COME LOOSE IN A CORNER THE VENT SHROUD IS NOT SITTING FLUSH. REMOVED THE SHROUD. THERE IS EXCESS MATERIAL THAT IS PUSHUNG UP AGAINST THE WIRES INSIDE THE FAN ASSEMBLY. TAAPED A STRAIGHT EDGE ALONG THE SHROUD. CUT EXCESS MATERIAL OFF WITH A MULTI TOOL. SECURED THE VENT SHROUD TO THE CEILING.				
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$39.00
Notes				
1) ok nw repair not replace				
time allowed as goodwill				

Submitted

Labor Amt	\$78.00
Parts & Freight	\$0.00
Total	\$78.00

Approved

Labor Amt	\$39.00
Parts & Freight	\$0.00
Total	\$39.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.