



# RECREATIONAL VEHICLES

Claim CLAIM4506 (KZ0041503)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	Repair VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Date of Purchase
CLAIM4506 (KZ0041503)	27180	5/18/2026	1/1/0001	4EZTL2727T4043110	CUST-002602		TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Pre-delivery 1/1/0001

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
	4401_03_A	R/R Interior Light Fixture, 12V - Improperly Installed - Repair/adjust/tighten	0.3	0.3	52.5	0 1	0.2	Approved
	<b>Complaint</b> Bedroom light switch is upside down <b>Cause</b> Noted on DAF <b>Correction</b> Remove light switch and install in correct position							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
	5521_01_A	R/R PANEL, WALL - Damaged - Repair/adjust/tighten	0.2	0.2	35	0 1	0	Approved
	<b>Complaint</b> Holes and stains on the pantry wall <b>Cause</b> Noted on DAF <b>Correction</b> Clean, fill, and color blend areas							

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet Qty	Base Hours	Status
	5559_01_A	Repair Drawer - Damaged - Repair/adjust/tighten	0.3	0.3	52.5	0 1	0.3	Approved
	<b>Complaint</b> Bathroom cabinet door to the left of the mirror is scratched <b>Cause</b> Noted on DAF <b>Correction</b> Fill and color blend area							

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	140.00	Approved labor & subLet	140.00
Submitted freight	0.00	Approved freight	0.00
<b>Total Submitted</b>	<u>140.00</u>	<b>Total approved</b>	<u>140.00</u>