

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<table border="0" style="width: 100%;"> <tr> <td style="width: 60%;">CLAIM STATUS</td> <td>Authorized</td> </tr> <tr> <td>CLAIM</td> <td>2665537</td> </tr> <tr> <td>CLAIM ORIGIN</td> <td>WEB</td> </tr> <tr> <td>ORIGINAL CLAIM ID</td> <td></td> </tr> <tr> <td>VIN</td> <td>4X4TCKV22TK099952</td> </tr> <tr> <td>CHASSIS VIN</td> <td></td> </tr> <tr> <td>MILEAGE</td> <td>0</td> </tr> <tr> <td>SITE/WAREHOUSE</td> <td>094 / 094A</td> </tr> <tr> <td>ITEM #</td> <td>CKT20RDSE-94</td> </tr> <tr> <td>DEALER RO #</td> <td>79706</td> </tr> <tr> <td>CLAIM START DATE</td> <td>05/05/2026</td> </tr> <tr> <td>CLAIM END DATE</td> <td>01/01/1900</td> </tr> </table>	CLAIM STATUS	Authorized	CLAIM	2665537	CLAIM ORIGIN	WEB	ORIGINAL CLAIM ID		VIN	4X4TCKV22TK099952	CHASSIS VIN		MILEAGE	0	SITE/WAREHOUSE	094 / 094A	ITEM #	CKT20RDSE-94	DEALER RO #	79706	CLAIM START DATE	05/05/2026	CLAIM END DATE	01/01/1900
CLAIM STATUS	Authorized																								
CLAIM	2665537																								
CLAIM ORIGIN	WEB																								
ORIGINAL CLAIM ID																									
VIN	4X4TCKV22TK099952																								
CHASSIS VIN																									
MILEAGE	0																								
SITE/WAREHOUSE	094 / 094A																								
ITEM #	CKT20RDSE-94																								
DEALER RO #	79706																								
CLAIM START DATE	05/05/2026																								
CLAIM END DATE	01/01/1900																								

Retail Date of Purchase	WARRANTY EXPIRATION DATE
--------------------------------	---------------------------------

Claim Line Details

Labor

Line# 1	Operation Code 40-570-01-11-001353	Operational Description Tank Sensor - Probe Pods, each - Electrical/Firefly Multiplex System/Replace/ Electrical
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2026-05-05 15:58:10 :: THE GREY TANK DOES NOT READ FULL REGARDLESS OF FLUID LEVEL. Filled grey tank until it backed up into the sink. The tank reads 2/3 full. Opened the underbelly and inspected the wires and diode pack. When I jumped the full sensor it read on the panel. Drained the tank. Installed a new sensor and filled the tank up again. The panel still doesn't read full. Replaced the diode pack and the panel still doesn't read full. After i filled the tank until it backed up in the sink, the next day the sink was empty. Filled it up again until I saw water in the sink. Now the tank reads full. Taped up underbelly and drained the tank..
Model#	NA	Dlr Sub Hrs 1.60 Sub Labor Amt \$312.00
Serial#	NA	Appr Hrs 1.00 Appr Labor Amt \$195.00
	Notes	Dealer has requested more time than what is normally approved for this repair. If you have additional information or need more time as the repair progresses, please contact me directly to discuss and I can continue to review it.

Labor

Line# 2	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2026-05-05 16:13:37 :: THE DOORS ABOVE THE SINK ARE RUBBING The cabinet doors are hitting each other. Moved doors away from each other with a hammer.
Model#		Dlr Sub Hrs 0.10 Sub Labor Amt \$19.50
Serial#		Appr Hrs 0.10 Appr Labor Amt \$19.50
	Notes	

Labor

Line# 3	Operation Code 20-43-19-00-004330	Operational Description Spot Seal Exterior (Dealer) - Exterior/Exterior Miscellaneous/Reseal/No Tread Code
	Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2026-05-05 16:14:18 :: THE SILICONE NEEDS TO BE TOUCHED UP. Gaps in silicone Applied silicone as needed to gaps around water heater and compartment door.
Model#		Dlr Sub Hrs 0.20 Sub Labor Amt \$39.00
Serial#		Appr Hrs 0.20 Appr Labor Amt \$39.00
	Notes	

Submitted	Labor Amt	\$370.50
	Parts & Freight	\$0.00
	Total	\$370.50

Approved	Labor Amt	\$253.50
	Parts & Freight	\$0.00
	Total	\$253.50

DEALER _____ **DATE** _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____

SIGNATURE

All repairs described have been inspected and are satisfactory.