

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13477B

Date In: 12 MAY 26 Author: KOTT  
Promised Date: 25 DEC 26 Stock No: 10787  
: Year: 2023  
Customer Name: 18062 - PETERS, THOMAS Manufacturer: GRAND DESIGN  
Address: 10228 SETTLEMENT LN Brand: REFLECTION FW  
: SISTER BAY, WI Model: 303RLS  
Postal/Zip: 54234 Miles/Hrs: 0  
Phone#(res): 9702141976 Exterior Color:  
Phone#(bus): Unit Type: FW-FIFTH WHEEL  
Cell Phone: License#:  
Email: outwestpilot@gmail.com Tag#: DB: 5/12  
Purchased Date: 07 MAY 26 :  
Delivery Date: 12 MAY 26 :  
InService Date: :  
Serial#: 573FR3425P9922405 :

```
*****  
Job # Description JOB INFORMATION Type Bill To  
*****  
6 COMPLAINT: PER MATT- THE SLIDE OUT IS LEAKING AND W 1020 GRAND  
NEEDS TO BE FIXED-  
CAUSE: I added silicone to the rails and at the  
bottom of the tray. I sprayed the slide  
down heavily with water and no leaks are  
visible.  
CORRECTION: Done. REQ: 1.43  
1 COMPLAINT: FOUND ON THE DAY OF SHOWTHRU- THE W 1020 GRAND  
OBSERVATION CAMERA IS NOT OPERATING-  
CAUSE: THE BLUE POWER INDICATOR LIGHT DOES NOT  
LIGHT UP- VERIFIED POWER TO THE CAMERA  
ALL CHECKED OKAY- THER IS ALSO NO WIFI  
CONNECTION TO THE CAMERA- INTERNAL  
FAILURE OF THE CAMERA0  
CORRECTION: R&R OBSERVATION CAMERA REQ: .75 HOURS  
OF LABOR  
2 COMPLAINT: FOUND ON THE DAY OF SHOWTHRU- THE W 1020 GRAND  
NAUTILUS PANEL IS CRACKED IN THE LOWER  
RIGHT CORNER  
CAUSE: NAUTILUS PANEL IS CRACKED FROM THE LOWER  
LEFT CORNER SCREW BEING SCREWED TO TIGHT  
CORRECTION: R&R NAUTILUS PANEL REQ! 1 HOUR  
3 COMPLAINT: FOUND ON DAY OF THE SHOWHTRU- BOTH OF W 1020 GRAND  
THE SADDLE BOXES ARE CRACKED AROUND THE  
SCREWS AND NEEDS TO BE REPLACED  
CAUSE: THE SADDLE BOXES ARE BOTH CRACKED AROUDN  
THE SCREWS FROM THE MANUFACTURER AND  
NEED TO BE REPLACED
```

Continued on page 2

Work Order : 13477B

\*\*\*\*\*  
 Job # Description JOB INFORMATION Type Bill To  
 \*\*\*\*\*  
 CORRECTION: R&R SADDLE BOXES REQ: 1.50 HOURS OF  
 LABOR

\*\*\*\*\*  
 Job # Part No Description PARTS Bill to Qty Price Total  
 \*\*\*\*\*  
 6 146877 NOVAFLEX SEALANT WHITE W-1020 1 9.28 9.28  
 2 EST 360041- CONVENIENCE CENTER W-1020 0 32.50 0.00  
 1 EST 740153- OBSERVATION REAR VI W-1020 0 32.50 0.00  
 3 822060039 SADDLE BOX 56" BLACK ABS HA W-1020 0 62.34 0.00

\*\*\*\*\*  
 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total  
 \*\*\*\*\*  
 6 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 140.00 70.00

\*\*\*\*\*  
 BILLINGS SUMMARY  
 Type Bill Id Parts Labour Sublet Extras Tax Total  
 \*\*\*\*\*  
 W 1020 9.28 70.00 0.00 0.00 0.00 79.28  
 Totals 9.28 70.00 0.00 0.00 0.00 79.28

&k2S  
 &k0S