

Pre-Authorization

Pre-Authorization number	PREAUTH112404(PA04003230)	Reference no.79808	Status	Approved
--------------------------	---------------------------	--------------------	--------	----------

Servicing Dealer 1194

Name Basden's American RV

Address 600 E Baseline Rd
Evansville, IN 47725

VIN 4YDTSGM23S7103030

Retail sold on 5/7/2026

Root		Approved			Actual		Base	Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
5101602A	Cord, 120V Shoreline - Detachable - Repair	0	0.3	0.3		1	0.2	Complaint: SHORE CORD IS AT AN ANGLE AND NEEDS FIXED Cause: Shore cord plug not in correct location Correction: Took plug out and rotated plug in cap and put it back in camper and sealed with clear silicone. Correct location now
6201002B	Pigtail - Replace	0	0.3	0.3		1	0.3	Complaint: LP LINE FROM TANK IS NOT LETTING LP GO THROUGH Cause: No lp from door side tank Correction: So i could not get any lp from doorside tank. So I switched to the other tank and everything works properly. So I took the lp line off the tank and found that the plastic gasket from inside the hose was broken. So I replaced the hose and system works properly now. And I did a leak check on my connection no leaks
Pre-Authorization number: PREAUTH112404				0.6				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.