

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 79808
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51345 - CYNTHIA FRANCIS
Address: 1234 COUNTY ROAD 800 E CARMI, IL
62821

Phone:

Stock Number: 11558 - 2025 SPRINGDALE 261BHC 4YDTSGM23S7103030

VIN: 4YDTSGM23S7103030 HIN: SER#: 4YDTSGM23S7103030

Mileage: 0 Work Order Comp: 20 MAY 26

Auth. No: Dealer #: 1194

Warr. Date: 07 MAY 26 Work Order Date: 04 MAY 26 Inv #: 430357

WO # Job # Description JOB INFORMATION

79808 4 LP LINE FROM TANK IS NOT LETTING LP GO THROUGH
No lp from door side tank
So i could not get any lp from doorside tank. So I switched to
the other tank and everything works properly. So I took the lp
line off the tank and found that the plastic gasket from inside
the hose was broken. So I replaced the hose and system works
properly now. And I did a leak check on my connection no leaks

79808 3 SHORE CORD IS AT AN ANGLE AND NEEDS FIXED
Shore cord plug not in correct location
Took plug out and rotated plug in cap and put it back in camper
and sealed with clear silicone. Correct location now

Part No	Job#	Description	PARTS	Qty	Price	Total
MECMER425-15P	4	MER425-15P 15"	PROPANE HOSE	1.00	24.95	24.95

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISCELLANEOUS REPAIR		0.30	190.00	57.00
Z990	3	MISCELLANEOUS REPAIR		0.00	190.00	0.00
Z990	3	MISCELLANEOUS REPAIR		0.30	190.00	57.00

Parts Total: 24.95
Labour Total: 114.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 138.95

Customer Signature: _____

Date: _____

Claim : 79808

```
*****
Lab Code  Job#  Description      LABOUR                      Hrs      Rate      Total
*****
```