

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2682654
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2LNHB3T9012029
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	501 / 501
OWNER INFORMATION		ITEM #	LNT185RB
DONALD CASUSE JR		DEALER RO #	72900
1412 VASSAR DR NE #C		CLAIM START DATE	05/20/2026
Albuquerque, NM 87106		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	01/31/2026	WARRANTY EXPIRATION DATE	01/31/2027

Claim Line Details

Labor

Line# 1	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-05-20 15:12:48 :: Front cap decal is peeling under window. Defective decal. Replace decal.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00
	Notes Could you please provide a more clear photo of the decal peeling? The decal that is peeling is the boomerang decal. The ends of it are lifting/peeling. If you zoom in you can tell they are supposed to be more pointed. On the left side of the boomerang, you can actually see that it is folded over, under the plastic protectant for the window. The right side is also peeled, the end should be pointier than it is. GOODWILL GESTURE			

Submitted	Labor Amt	\$95.00	Approved	Labor Amt	\$95.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$95.00		Total	\$95.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.