



RECREATIONAL VEHICLES

Claim CLAIM4805 (KZ0041804)

Last Modified By

| Claim | Reference no. | Repair start date | Repair date | VIN | Pre-auth Dealer | Repairing dealer name | Labor rate | Changed warranty | | Date of Purchase |
|--------------------------|---------------|-------------------|-------------|-------------------|-----------------|--|------------|------------------|--------------|------------------|
| | | | | | | | | rate | Type | |
| CLAIM4805 (KZ0041804) | 27198 | 5/21/2026 | 1/1/0001 | 4EZTL332XT4042917 | CUST-002602 | TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711 | 175.00 | 175.00 | Pre-delivery | 1/1/0001 |

| Deny code | Operation | Description | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status |
|-----------|-----------|--|-----------|------------|-----------|--------|-----|------------|----------|
| | 5536_01_A | Repair TV Cabinet - Damaged - Repair/adjust/tighten Complaint Seam tape over tv location is loose Cause Noted on DAF Correction Resecure seam tape back in place | 0.2 | 0.2 | 35 | 0 | 1 | 0 | Approved |

| Deny code | Operation | Description | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status |
|-----------|-----------|---|-----------|------------|-----------|--------|-----|------------|----------|
| | 5540_01_A | Repair, General, Putty, Clean, Sand, Etc. - Damaged - Repair/adjust/tighten Complaint Living room slide fascia has several holes and faded spots Cause Noted on DAF Correction Fill, color, and blend areas | 0.2 | 0.5 | 87.5 | 0 | 1 | 0.1 | Approved |

| Deny code | Operation | Description | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status |
|-----------|-----------|--|-----------|------------|-----------|--------|-----|------------|--------|
| | 5540_07_A | Repair, General, Putty, Clean, Sand, Etc. - Gaps / Voids - Repair/adjust/tighten Complaint Chip on cabinet near handle in the kitchen area Cause Noted on DAF Correction Fill, color, and blend area | 0.2 | 0 | 0 | 0 | 1 | 0.1 | Denied |

| Deny code | Operation | Description | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status |
|-----------|-----------|---|-----------|------------|-----------|--------|-----|------------|--------|
| | 5540_02_A | Repair, General, Putty, Clean, Sand, Etc. - Delam/Peeling/Flaking - Repair/adjust/tighten Complaint Chip on kitchen pantry door Cause Noted on DAF Correction Fill, color, and blend area | 0.2 | 0 | 0 | 0 | 1 | 0.1 | Denied |



RECREATIONAL VEHICLES

Claim CLAIM4805 (KZ0041804)

Last Modified By

| Deny code | Operation | Description | Sub hours | Apvd Hours | Labor amt | Sublet Qty | Base Hours | Status |
|-----------|---|-----------------------------|-----------|------------|-----------|------------|------------|--------|
| 5540_01_A | Repair, General, Putty, Clean, Sand, Etc. - Damaged - | Repair/adjust/tighten | 0.2 | 0 | 0 | 0 | 1 0.1 | Denied |
| | Complaint | Chip on wall next to pantry | | | | | | |
| | Cause | Noted on DAF | | | | | | |
| | Correction | Fill, color, and blend area | | | | | | |

| | | | |
|-------------------------------------|---------------|------------------------------------|---------------|
| Submitted parts & subLet | 0.00 | Approved parts & subLet | 0.00 |
| Submitted labor & subLet | 175.00 | Approved labor & subLet | 122.50 |
| Submitted freight | 0.00 | Approved freight | 0.00 |
| Total Submitted | <u>175.00</u> | Total approved | <u>122.50</u> |