



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27059



WO #: 27059

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11184

Stock Desc: 2026 FW FOREST RIVER

SANDPIPER 3370RLS

Model: 3370RLS

Serial #: 4X4FSAK20TJ048566

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 24 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: ENTRY SCREEN DOOR IS NOT OPENING FROM THE INSIDE AS DESIGNED TO DO.
CUSTOMERS WERE LOOKING AT UNIT AND COULD NOT GET THE SCREEN DOOR TO OPEN.

CAUSE: SCREEN DOOR IS FAULTY, BENT AND TWISTED FROM FACTORY BUILD
WHEN SHUTTING THE SCREEN YOU CAN FEEL IT PULL AT THE BOTTOM

CORRECTION: REPLACE SCREEN DOOR
LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR WINDOW IS CHANGING COLORS

CAUSE: TECH VERIFIED WINDOW IS CHANGING IN COLOR AND DEFECTIVE FROM FACTORY

CORRECTION: REPLACE WINDOW
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ON THE WINDOW TO THE LEFT OF THE ENTRY DOOR HAS A SEAL THAT IS COMING
LOOSE FROM WINDOW. THE SEAL WILL NOT STAY IN CORRECTLY.

CAUSE: DEFECT IN WINDOW SEAL.

CORRECTION: REPLACE WINDOW
LABOR 1.0

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE SIDE WINDOW IN THE LIVING SLIDE OUT HAS VINYL STRIP THAT IS SHRINKING
ON THE LEFT SIDE OF THE WINDOW.

CAUSE: DEFECT IN THE WINDOW

CORRECTION: REPLACE WINDOW

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR 1.0

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: SMALL WINDOW TO THE RIGHT OF THE ENTRY DOOR HAS A DEFECT IN THE WINDOW SEAL AND IS COMING LOOSE. SEAL IS NOT STAYING IN PLACE CORRECTLY.

CAUSE: DEFECT IN WINDOW

CORRECTION: REPLACE WINDOW
LABOR 1.0

Subtotal for Job #5: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 22 May 2026

W/O: 27059



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

