



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64904
Promised Date: 31 AUG 21

CUSTOMER WORK ORDER

WO #: 64904 (Appointment Date: 17 AUG 2021 - Time: 10:00am)

Customer: 13010 - KELLER, JOSEPH L. - Stock #: 10967

Tag: Stock Desc: 2021 5W KEYSTONE

Author: BJW COUGAR HALF-TON 30RLS

Location: 0830 CHECK STATUS Chassis #: 4YDF30R2XM2510921

Serial #: 4YDF30R2XM2510921

Mileage:

Licence:

Invoice #: 367040

Date In: 02 AUG 21

Promised: 31 AUG 21

Date Sched:

Completed: 31 AUG 21

Warr. Date: 11 MAY 21

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THAT THE EXHAUST FAN STARTED COMING ON BY ITSELF AND IT WOULD NOT TURN OFF. CUSTOMER WAS ADVISED BY CAMPING WORLD ON A RECENT TRIP TO CUT THE POWER SUPPLY WIRES TO TURN FAN OFF.

CORRECTION: INSTALLED NEW SWITCH AND PUT BACK SCREEN AND COVER

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	130.00

Parts

Part #	Description	Qty	Price	Total
212097	S731 PUSH BUTTON ON-OFF SWITCH	1.00	5.84	5.84

Subtotal for Job #1: 135.84

Job #2 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THIN SHADE INSTALLED ON THE ENTRY DOOR.
NOTE: PART IS UNDER THE SHELF NEAR BWS CHAIR.

CORRECTION: INSTALLED SHADE IN DOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	N/C

Parts

Part #	Description	Qty	Price	Total
786037	Thin Shade_ Ready RV Window Shade for Prepped LCI Entry Doors	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE CAULKING ON THE LEFT FRONT CORNER OF THE 5TH WHEEL OVERHANG IS MISSING.

CUSTOMER STATES THAT THERE IS A SCREW BACKING OUT FROM UNDER THE UNIT WHERE THE BLACK TRIM RUNS FROM UNDER THE FIFTH WHEEL DOWN THE COACH AND UNDER THE UNIT. SEE WRITER FOR DETAILS.

CORRECTION: RE SEALED MOLDING

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 13010
KELLER, JOSEPH L.



Z999 MISCELLANEOUS REPAIR BB 130.00

Subtotal for Job #3: 130.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES THAT THE VENT LID DOES NOT GO DOWN ALL THE WAY IN THE BATHROOM. THIS IS THE VENT THAT WE ADDED THE MAXAIR TO.

CORRECTION: MOVED MAX AIR COVER UP TO SHUT RIGHT+

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	39.00

Subtotal for Job #4: 39.00

Job #5 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE 80 PSI IN ALL TIRES.

CORRECTION: PUT 80 PSI IN ALL FOUR TIRES

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Job #6 - External

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE A PRICE ON ADDING TPMS.

CORRECTION: WIRED UP AND INSTALLED CONTROL BOX . MOUNTED FOUR CONTROLERS ON STEMS

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Parts

Part #	Description	Qty	Price	Total
5382	TIRE LINC TIRE PRESSURE AND TEMPERATURE MONITORING SYSTEM	1.00	N/C	N/C

Subtotal for Job #6: 0.00

Parts Total: 5.84
 Labour Total: 299.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 304.84

Thank you for being a valued customer. We appreciate your business.
 All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 64904
 Promised Date: 31 AUG 21



Customer #: 13010
 KELLER, JOSEPH L.



Customer Signature : _____

Date: 31 Aug 2021

W/O: 64904
Promised Date: 31 AUG 21



Customer #: 13010
KELLER, JOSEPH L.



Customer Order

