

BASDEN RV CENTER, INC dba AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 79960  
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
 Customer: 56809 - MICHAEL COTTON  
 Address: 5411 CRESTWOOD DR. NEWBURGH, IN

47630

Phone: 812-457-4757

Stock Number: 11714 - 2026 COUGAR SPORT 2700BH 4YDFCGN29T2504783

VIN: 4YDFCGN29T2504783 HIN: SER#: 4YDFCGN29T2504783

Mileage: 0 Work Order Comp: 27 MAY 26

Auth. No: Dealer #: 1194

Warr. Date: 21 MAY 26 Work Order Date: 18 MAY 26 Inv #: 430565

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*

79960 2 BATTERY DISCONNECT BROKE AND WILL NOT TURN  
 Battery disconnect broken  
 I put in a parts request for a new one and i got it replaced and  
 it works properly

79960 3 LP SYSTEM IS LEAKING. UNIT IS NOT PASSING MANOMETER TESTING.  
 Lp leak found during drop test  
 So during my lp drop test I found that I had a leak when I was  
 trying to hold 8 for 5min. So I sprayed all my connections and  
 nothing showed up. So then I plugged off the line to the stove.  
 No change. Then the water heater not change then the furnace no  
 change. I switched gauges no change. So then I had the only lp  
 appliances capped off then I started spraying the connections  
 again I finally found it the 90 degree elbow coming from the  
 other tank. So I took it off cleaned the threads on both and  
 applied pipe dope and tightened it up. Then I pressurize the  
 system and gauge showed no leaks. So then I connected all my  
 appliances spray checked them and no leaks. System is working  
 properly

\*\*\*\*\*  
 Part No Job# Description PARTS Qty Price Total  
 \*\*\*\*\*  
 721714 2 Box - 12v Power Distribution - FW 1.00 136.64 136.64

\*\*\*\*\*  
 Lab Code Job# Description LABOUR Hrs Rate Total  
 \*\*\*\*\*  
 Z990 2 MISCELLANEOUS REPAIR 0.50 190.00 95.00

Claim : 79960

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISCELLANEOUS REPAIR          0.00    190.00     0.00
Z990      2    MISCELLANEOUS REPAIR          0.50    190.00    95.00
Z990      3    MISCELLANEOUS REPAIR          1.00    190.00   190.00

```

```

*****
Excode    Job#  Description          EXTRAS          Qty      Price     Total
*****
FRT       2    UPS-BOX                1.00     12.62    12.62

```

Parts Total: 136.64  
 Labour Total: 380.00  
 Sublet Total: 0.00  
 Extras Total: 12.62

>>>> Claim Total: 529.26

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_