



KEYSTONE

Pre-Authorization

Pre- Authorization number: PREAUTH113578 (PA04004363) Reference no. 79960 Status: Approved

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd VIN 4YDFCGN29T2504783 Retail sold on 5/21/2026
Evansville, IN 47725

Root	Operation Description	Sublet	Sub Hours	Actual Hours	Qty	Base hours	Complaint/Cause/Correction
5109006B	Battery Disconnect - All Types	0	0.3	0.3	1	0.3	<p>Complaint: BATTERY DISCONNECT BROKE AND WILL NOT TURN</p> <p>Cause: Battery disconnect broken</p> <p>Correction: I put in a parts request for a new one and i got it replaced and it works properly</p>
6201006B	Pigtail - Replace	0	2	1	1	0.3	<p>Complaint: LP SYSTEM IS LEAKING. UNIT IS NOT PASSING MANOMETER TESTING.</p> <p>Cause: Lp leak found during drop test</p> <p>Correction: So during my lp drop test I found that I had a leak when I was trying to hold 8 for 5min. So I sprayed all my connections and nothing showed up. So then I plugged off the line to the stove. No change. Then the water heater not change then the furnace no change. I switched gauges no change. So then I had the only lp appliances capped off then I started spraying the connections again I finally found it the 90 degree elbow coming from the other tank. So I took it off cleaned the threads on both and applied pipe dope and tightened it up. Then I pressurize the system and gauge showed no leaks. So then I connected all my appliances spray checked them and no leaks. System is working properly</p>

Pre-Authorization number: PREAUTH113578

1.3

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.