



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79985



CUSTOMER WORK ORDER

WO #: 79985 (Appointment Date: 20 MAY 2026 - Time: 09:30am)

Customer: 27972 - WEAVER, SAM -
812-499-2118

Tag:
Author: GA
Location: 0522 BH TO CLOSE

Stock #:
Stock Desc: 2026 5W KEYSTONE
COUGAR 316RL
Chassis #:
Serial #: 4YDFCGR24T2501333
Mileage:
Licence:

Invoice #:
Date In: 20 MAY 26
Promised:
Date Sched:
Completed: 22 MAY 26
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SMALLER AWNING THAT COMES OFF OF THE SLIDE ROOM ON THE DOOR SIDE GOES OUT SLOWLY AND IT JERKS. IT WILL GO BACK IN. IT ONLY DOES THIS WITH THE SWITCH AT THE INTERIOR CONTROL PANEL. CUSTOMER CAN RUN IT FROM THE SWITCH IN THE PASSTHROUGH AND IT FUNCTIONS PROPERLY.

CAUSE: Awning not working on interior switch

CORRECTION: Brought unit in. Opened compartment door and ran slideroom awning in and out. Awning works as should. Went inside and tried to use awning switch. Awning jerks and spots and repeats process. Removed switch from panel. The connection on the extend part of switch has loose connection that has been pulled out. Parts request submitted for new switch. Received new switch. Removed cover on board. Removed screws holding board in. Pulled old switch out and replaced with new switch. Tested awning. Awning no longer jerks in and out when using switch inside. Placed screws back in board and cover back on

Customer #: 27972
WEAVER, SAM



Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	26.60
Z990	MISCELLANEOUS REPAIR	CCV	68.40

Parts

Part #	Description	Qty	Price	Total
401870	Switch - 10 Amp - SPDT - On/Off/On -	1.00	4.55	4.55

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	12.62	12.62

Subtotal for Job #1: 112.17

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE LOCK ON THE FRIDGE DOESN'T LATCH

CAUSE: Fridge lock

CORRECTION: Brought unit in. Grabbed fridge lock that screws into the top of fridge. Lined up lock and started to thread into place. Once started tightened all the way down until doors work locked in place. Left lock in for customer to see.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	38.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #2: 38.00

W/O: 79985

Parts Total: 4.55
Labour Total: 133.00
Sublet Total: 0.00
Extras Total: 12.62

WORK ORDER TOTAL: 150.17

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 22 May 2026

Customer Signature : _____

Customer Work Order



Customer #: 27972
WEAVER, SAM

