



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26984



WO #: 26984 (Appointment Date: 15 APR 2026 - Time: 01:00pm)

Customer: 92564 - WHITTEN, SANDY
Address: 2919 MAIN ST
SURGOINSVILLE, TN
37873

Home Phone: (423) 327-5008

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11021

Stock Desc: (11021) 2025 KZ-RV SPORTSMEN

SEL 260BHSL

Model: 260BHSL

Serial #: 4EZTU2520S5076264

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 14 MAR 25

Date In: 13 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 MAY 26

Warr. Date: 14 MAR 25

Job #1 - Warranty

COMPLAINT: CS THAT THE WATER HEATER IS LEAKING BEHIND THE POP OFF VALVE

CAUSE: POP OFF VALVE HAS A STEADY STREAM LEAK OFF BACK SIDE

CORRECTION: REPLACE THE POP OFF VALVE AND RETEST

LABOR AND DIAG 1.0

AFTER REPLACEMENT OF POP OFF VALVE TECH FOUND THE SENSOR NEEDED TO BE
REPLACED AS WELL

Labor

Job #	Description	Hours	Total
1	MISC. LABOR CODE	0.75	131.25

Parts

Part #	Description	Qty	Price	Total
506228	VALVE,PRESS RELIEF,WTR HTR,F/164594	1.00	51.79	51.79

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	22.50	22.50

Subtotal for Job #1: 205.54

Parts Total:	51.79
Labour Total:	131.25
Sublet Total:	0.00
Extras Total:	22.50
WORK ORDER TOTAL:	205.54

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 May 2026

Customer #: 92564
WHITTEN, SANDY

