

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Paid CLAIM 2677451 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2AVFC0TG815460 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 452 / 452 ITEM # AVT17DBX-452 DEALER RO # 73356 CLAIM START DATE 05/15/2026 CLAIM END DATE 05/18/2026
Labor rate: \$190.00 OWNER INFORMATION ANTHONY KLINE 4006 HILTON AVE NE Albuquerque, NM 87110 USA	
Retail Date of Purchase 05/16/2026	WARRANTY EXPIRATION DATE 05/16/2027

Claim Line Details

Labor

Line# 1	Operation Code 30-474-12-00-003344	Operational Description Bracket - Interior/Appliance Securement/Resecure or Tighten/No Tread Code
	Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-05-15 12:48:54 :: Complaint: Refrigerator is loose Cause: Found refer came loose from rear mounting bracket. Found a self tapping screw drilled through the bottom hinge on the left side of the refer door to hold it into the hole. Remove the screw and pull the refer out to examine the mounting bracket, found it was still screwed into the floor. However, putting the refer back in to test the mounting bracket it was found that the refer would go too far into the cabinet not allowing the door to be opened. Correction: Move the mounting bracket forward about one inch. Now the refer will not tip out or tip forward. The original screw that was run though the hinge was put back into place.
Model#	Dlr Sub Hrs 0.70	Sub Labor Amt \$133.00
Serial#	Appr Hrs 0.70	Appr Labor Amt \$133.00
	Notes Authed	

Submitted	Labor Amt \$133.00	Approved	Labor Amt \$133.00
	Parts & Freight \$0.00		Parts & Freight \$0.00
	Total \$133.00		Total \$133.00

DEALER _____ **DATE** _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.