

Tag Number: _____

Estimate No. 1585

Estimate Date: May 14 26



Customer: Myers RV Center

12024 Central Ave SE

Albuquerque NM 87123

Oxidation RV Repair Service

4516 2nd St NW

Albuquerque, NM 87107

505-417-9386

oxidationrv@gmail.com

Make: R Pod Hood River ^{edition} Model: _____

Year: 2026 VIN: 4X4TRPU19TB036853

Estimate		Amount
3.0	Repair Strees cracks Passenger side front Bottom corner wall	
1.0	R-R Comp Door p/side Front	
1.0	R-R Bottom Molding	
1.5	Mask prep prime Door, wall Bottom Gray color	
2.0	paint / clear	
8.5		
putty	Paint Mix	282.5
silicone	Waste Disposal	10.00
	Shop Supplies	10.00
	Labor	654.5
	Parts	
	Misc.	
	Subtotal	\$ 957.00
	Sales Tax	
	Total	957.00

Adjuster Name: _____

Claim Number: _____

Telephone No. _____

Customer Signature: BR

Date: 5/14/26