

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2662654
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TRPV24TB036671
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT203-80
		DEALER RO #	73302
		CLAIM START DATE	05/04/2026
		CLAIM END DATE	05/20/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-57-24-00-000601	Operational Description Sidewall - Exterior/Exterior Fiberglass Walls/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-05-04 09:29:40 :: Complaint: Repair front fiber glass, spider cracks Cause: There are spider cracks in the front fiberglass Correction: No impact damage, sublet for repair and repaint	
Model#	Dlr Sub Hrs 0.00	Sub Labor Amt \$570.00
Serial#	Appr Hrs 0.00	Appr Labor Amt \$565.00

Notes

hello, I am not seeing this issue noted on the DAF - is there anything behind the damage that would make the wall buldge out and cause the spider cracks?
We can't tell without taking it apart. It was very hard to see unless you were right on top of it, it blended it.
Hello, in the first few pictures there doesn't appear to be any spider cracks or a gash, however in the 3rd picture there is spider cracking and a gash. Please advise.
These spider cracks/gash were incredibly hard to see. We never saw it until the unit was washed and the sun was shining on that side. You had to be straight in front and close to even see it. The pictures were taken at different angles, and with the glare, and how hard it was to see in person, that is likely why they don't show up in the first two pictures.
Authorized sublet. Please note, we do not cover waste disposal.
changed to a more suitable code for this repair.

Submitted	Labor Amt	\$570.00	Approved	Labor Amt	\$565.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$570.00		Total	\$565.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.