



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65184

CUSTOMER WORK ORDER

WO #: 65184

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0915CHECK WORK

Stock #: 10716

Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 303BH

Chassis #: 4YDTSGP24N3100385

Serial #: 4YDTSGP24N3100385

Mileage: 0

Licence:

Invoice #:

Date In: 07 SEP 21

Promised:

Date Sched:

Completed: 18 SEP 21

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Purged and filled LP tanks. Installed new battery box and drilled drain holes in bottom. Installed longer neg. battery cable to reach battery box. Relocated brake-away switch to clear hitch brackets. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Operater all electric stab jacks. Checked roof and awning. Checked both entrance doors and all compartment doors. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Removed packing on all appliances. Checked all electrical outlets and both GFCI circuits. Checked all USB outlets. Checked converter output. Added water to fresh water tank and flushed antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Filled all holding tanks and checked monitor panel. Checked TV, TV Antenna, Radio/DVD/CD Player and Fireplace. Checked all appliances. Checked all TV cable locations. Applied all company decals. Recorded all serial numbers and took pictures. Dumped all holding tanks, including water heater. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: WIRES HANGING DOWN UNDER LIVING ROOM SLIDE

CAUSE: WIRES HANGING DOWN UNDER LIVING ROOM SLIDE.

CORRECTION: Checked wires hanging down. Screw holding end of support spring broken off. Drilled hole and installed larger screw to anchor end of support spring. Reattached wire loome to support spring with wire ties. Checked operation of slideout and spring mount. Ok

Labor



Customer #: 1000
BASDEN'S AMERICAN RV,



Code Description
Z990 MISCELLANEOUS REPAIR

Mechanic Total
DKM 26.00

Subtotal for Job #1: 26.00

Parts Total: 0.00
Labour Total: 26.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 26.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 18 Sep 2021

Customer Signature : _____

W/O: 65184



Customer #: 1000
BASDEN'S AMERICAN RV,



Pre-Authorization

9/18/20
10:44:09

Pre-Authorization number PA02933826	Reference no: 65184	Status: Approved	Approved by rod	Approved date 9/17/2021
Customer Name	Address	VIN	Retail sold on	

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGP24N3100385
----	----------------------	---	-------------------

Item	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2106714A	Slide Out Box W/r	0.00	0.90	0.20		1	0.20	Complaint: WIRES HANGING DOWN UNDER LIVING ROOM SLIDE Cause: WIRES HANGING DOWN UNDER LIVING ROOM SLIDE.

Correction: Checked wires hanging down. Screw holding end of support spring broken off. Drilled hole and installed larger screw to anchor end of support spring. Reattached wire hrome to support spring with wire ties. Checked operation of slideout and spring mount. OK
KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

Pre-Authorization number PA02933826

0.20

Customer paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the