

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 65277
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 49486 - KRISTIE R. SWENSON
Address: 312 CHARMWOOD CT EVANSVILLE, IN

47715

Phone: 301-919-1027

Stock Number: 10921 - 2021 MONTANA HIGH COUNTRY 377FL 4YDF37723MA742696

VIN: 4YDF37723MA742696 HIN:

SER#: 4YDF37723MA742696

Mileage: 0

Work Order Comp: 20 DEC 21

Auth. No:

Dealer #: 1194

Warr. Date: 05 FEB 21

Work Order Date: 20 SEP 21

Inv #: 371533

WO #	Job #	Description	JOB INFORMATION

65277	1	CUSTOMER STATES THAT THE LEVELING SYSTEM IS NOT FUNCTIONING PROPERLY REAR SENSOR IS SHOWING ON THE CONTROL PANEL ISSUES CALL LCI AND THEY ARE TELLING ME TO REPLACE THE CABLE AND THE EXTERNAL SENSOR INSTALLED NEW REAR SENSOR AND CABLE AND CHECKED OPERATION AND RESET ZERO POINT.	
65277	2	CUSTOMER STATES THAT THE DOOR SIDE LIVING ROOM SHADE DOES NOT STAY DOWN. CUSTOMER STATES THAT THE DOOR SIDELIVING ROOM SHADE DOES NOT STAY DOWN. Unit on storage. 11/30/2021: Went to unit to replace night shade. Unboxed new shade. Wrong shade was sent. New shade is a double roll up. Old shade is a single roll up. SHAWN INSTALLED NEW CUSTOMERS BLIND THAT WONT STAY DOWN. NEW BLIND WORKS AS SHOULD CHECK PICTURES	

Part No	Job#	Description	PARTS	Qty	Price	Total

350744	1	Jack - Remote Rear		1.00	174.14	174.14
383820	1	Jack - Wire Harnes		1.00	62.15	62.15
663734	2	Shade - Roller - N		1.00	51.57	51.57

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total

Z990	1	MISCELLANEOUS REPAIR		0.00	130.00	0.00

Claim : 65277

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      1    MISCELLANEOUS REPAIR      0.50     130.00     65.00
Z990      2    MISCELLANEOUS REPAIR      0.10     130.00     13.00
Z990      2    MISCELLANEOUS REPAIR      0.10     130.00     13.00
Z990      2    MISCELLANEOUS REPAIR      0.00     130.00      0.00
Z990      2    MISCELLANEOUS REPAIR      0.00     130.00      0.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       1    UPS-JACK SENSOR AND HARNESS      1.00     12.54     12.54
FRT       2    UPS-SHADE                        1.00     36.73     36.73

```

```

Parts Total:      287.86
Labour Total:      91.00
Sublet Total:      0.00
Extras Total:      49.27

```

```

>>>> Claim Total:      428.13

```

Customer Signature: _____

Date: _____