



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79642
Promised Date:
05 APR 26

CUSTOMER WORK ORDER

WO #: 79642

Customer: 56690 - COX, JR., JOHN -
812-304-7184

Tag:

Author: BH

Location: 0427 CHECK PREAUTH

Stock #: 11556

Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 240RB

Chassis #: 4YDTSGL23S7103014

Serial #: 4YDTSGL23S7103014

Mileage:

Licence:

Invoice #:

Date In: 20 APR 26

Promised: 25 APR 26

Date Sched:

Completed: 27 APR 26

Warr. Date: 25 APR 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: New final

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires and installed monster seal. Installed a new battery. Running lights and tail lights work properly except off door side front top Running light. Brakes and Emergency Brakes work properly. Exterior inspection looks good. Roof inspection looks good. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection. Put water in the fresh tank and ran the water pump. Water pump kept running and stopping tried to adjust and it didn't fix the issue. So i am going to replace the water pump. I replaced the water pump and it works properly now. Stove works properly microwave works properly both refrigerators work properly ac works properly furnace works properly water heater works properly. Did my lp drop test on outside port with no adjustments to regulator system works properly. Tv antenna works properly. Drained black tank and gray tank and left 1/3 in the fresh tank for demonstration.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
10-7090	1pc 1/2" PLUG CAP	2.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Customer #: 56690
COX, JR., JOHN





Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work
 New hitchwork installation

CORRECTION: Installed the hitch brackets on the camper and put the rest of the hitch in side compartment. Drove the vehicle to the walk thru. Leveled the camper and checked the ball height and matched the truck. Connected the truck to the camper and adjusted as necessary. Tightened all hardware. Connected the 7-way plug, safety chains and breakaway cable.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: Monster seal

CORRECTION: Jacked up each tire and let the air out. And pumped in the monster seal then added correct air pressure. All 5 tires have monster seal and stickers are on the camper

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #MONSTER: 0.00

Job #1 - Internal

MAXXGAURD - WASHBAY

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: RUNNING LIGHT IS OUT OFF DOOR FRONT TOP.

CAUSE: Off door side top front running light doesn't work

CORRECTION: On my inspection of the lights i found that this one didn't work. I tested the wires and i had power there. So i replaced the the light and it works properly now. I put budle tape on the backside where the screws go through and i sealed up the outside with clear silicone. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	76.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts



Part #	Description	Qty	Price	Total
563371	Light - Clearance - 12V - LED - Rect	1.00	2.37	2.37
Subtotal for Job #2:				78.37

Job #3 - Warranty

COMPLAINT: WATER PUMP WILL NOT KEEP PRESSURE TRIED TO ADJUST WILL NOT ADJUST

CAUSE: Water pump does work properly

CORRECTION: The factory water pump ran and shut off. Didn't stay running the whole time when i had the faucet open and it made the water heater not work properly. We tried to adjust the factory pump but it didn't help. So i installed a new water pump. It works properly and water heater works properly. No leaks. Good to go

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	57.00

Parts Part #	Description	Qty	Price	Total
186592	(KEYSTONE) FLOJET	1.00	64.35	64.35
Subtotal for Job #3:				121.35

Parts Total:	66.72
Labour Total:	133.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	199.72

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Apr 2026

W/O: 79642
Promised Date: 25 APR 26



Customer #: 56690
COX, JR., JOHN

