Warranty Authorization Form

Date: 3/16/2026

Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Ph. 715-325-5170

mail@greenewayrv.com

General Information

Pre-Auth #: 935386 Unit: 573FM4123PBB00142

Series: Momentum Model: MT351MS-2023

Notes: AB 3/16 *Please hold all parts for a minimum of 30 days after the claim is paid*

Status: Approved

Dealer Information

1127 Greeneway RV Sales & Service
715-325-5170
mail@greenewayrv.com

Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Requestor: iclaim services
Return Fax #: (715) 325-5577
Email: greeneway@dealer-advisors.com

Operation Line 1

Flat Rate Code: 160021 Electric Leveling - R&R Wiring *Fault Code:* Damaged/Maintenance Harness

Serial #: *Model #:* *Notes:*

Problem: The generator that was mentioned on the previous PA was brought to Cummins as instructed. The problem is not the generator but the wiring harness behind the generator that was installed by Grand Design. The stated that the wiring harness is crumbled up behind the generator. The dealership did not have the ability to move the generator from its location. The unit is currently still at Cummins and they will do this work once approved.

Time Requested: 0

Time Allowed: 0

Sublet Repairs: 953.70

Cause: Wiring harness is crumbled up from install.

Remedy: The wiring harness needs to be replaced.

Status: Approved